

1272  
2640

Ancient Monuments Laboratory  
Report 1/90

ANALYSIS OF PLASTER SAMPLES FROM  
CLEEVE ABBEY, SOMERSET.

J G McDonnell BTech PhD MIFA

AML reports are interim reports which make available the results of specialist investigations in advance of full publication. They are not subject to external refereeing and their conclusions may sometimes have to be modified in the light of archaeological information that was not available at the time of the investigation. Readers are therefore asked to consult the author before citing the report in any publication and to consult the final excavation report when available.

Opinions expressed in AML reports are those of the author and are not necessarily those of the Historic Buildings and Monuments Commission for England.

Ancient Monuments Laboratory Report 1/90

ANALYSIS OF PLASTER SAMPLES FROM  
CLEEVE ABBEY, SOMERSET.

J G McDonnell BTech PhD MIFA

**Summary**

Degrading wall plaster was analysed by Scanning Electron Microscopy. This showed that NaCl crystal growth was present in the plaster and was probably responsible for the degradation.

Author's address :-

J G McDonnell BTech PhD MIFA

Ancient Monuments Laboratory  
English Heritage  
23 Savile Row  
London  
W1X 2HE

# **Analysis of Plaster Samples from Cleeve Abbey, Somerset**

**Dr Gerry McDonnell**

## **1 Introduction**

Cleeve Abbey has some well preserved medieval wall paintings on the plastered walls of the Church. In some areas the plaster is erupting, and blistering, which if it continues will lead to the loss of some paintings. The Conservation Studio requested that the cause of the plaster degradation be investigated. This report is one part of that investigation and covers the chemical/mineral analysis of the plaster.

## **2 Methods of Analysis**

Two samples of mortar from the affected areas were examined by X-Ray Powder Diffraction (XRD) to determine the major mineral components of the plaster and by Scanning Electron Microscope (SEM) to examine the inclusions present in the mortar.

## **3 Results**

### **3.1 XRD Analysis**

The XRD pattern produced by both mortar samples showed the presence of silica (sand) and calcite. There was no evidence for the presence of other major minerals. The technique cannot identify the presence of organic components in the plaster. The sand/calcite mix is typical of a lime mortar or plaster.

### **3.2 SEM Analysis**

A sample of each mortar and a sample of local slate were mounted on stubs, coated with carbon (to make them conducting) and examined in the SEM. Energy dispersive X-ray analysis was used to qualitatively examine the chemical composition of the slate sample and the inclusions in the mortar. The texture of the mortar was also investigated. Analysis of the inclusions showed them to be similar to the local slate sample, but there was considerable variation in composition (Figure 1), particularly in the presence/absence of iron and manganese. Analysis of the local slate detected the presence of titanium, which was absent from the inclusions in the mortar, but given the variation already observed between inclusions, small variations in all elements must be expected. Therefore, no firm conclusion can be drawn about the source of the inclusions without further detailed analysis.

Examination of the inclusions and the mortar/inclusion interface showed that there was no evidence for chemical reactions, eg the growth of sulphides etc, that might cause the eruptions on the mortar surface.

Further examination of the mortar showed the presence of cubic crystals (Plates 1-3). Spot analysis of the crystals identified them as sodium chloride (Figure 2).

#### **4 Discussion**

XRD analysis gave no indication as to the cause of the blistering, the mortar being a typical sand/calcite mix. SEM analysis showed that there was no reaction between the slate inclusions and the mortar, but crystals of sodium chloride were identified.

#### **5 Conclusions**

The blistering of the mortar surface is probably due to the growth of sodium chloride crystals in the mortar, caused by fluctuating Relative Humidity (RH), and/or rising damp.




Plate 1  
SEM micrograph of  
mortar showing  
growth of crystals  
(white) in centre  
and lower left of  
field of view (x87.6).




Plate 2  
Centre of plate 1 at  
increased magnification  
(x360)



Plate 3  
Detail of crystals,  
note cubic form (x1390)

Figure 1  
Comparison of  
two inclusion  
analyses




Figure 2  
Analysis of  
cubic crystals

