

SOU1516 A.2009.25 SAS 427 disc index

Folder: **SOU1516_documents**

Microsoft Office Word 2003 files

SOU1516_SCC_Building_Recording_WSI_New_Inn_16_Bevois_Valley_Road.doc

SOU1516_Building_Recording_Programme_of_Archaeological_Works.doc

SOU1516_Report.doc

SOU1516_Site_Summary.doc

Folder: **SOU1516_plans**

AutoCAD 2002 files

SOU1516_location_plan.dwg

SOU1516_ground_floor_plan.dwg

SOU1516_ground_floor_photo_locations.dwg

SOU1516_first_floor_plan.dwg

SOU1516_first_floor_photo_locations.dwg

SOU1516_external_photo_locations.dwg

Folder: **SOU1516_photos**

JPEG files

SOU1516_4-01_New_Inn_from_outside_Gurdwara.jpg

SOU1516_4-02_Coach_House_frontage.jpg

SOU1516_4-03_Coach_House_from_corner.jpg

SOU1516_4-04_New_Inn_and_terrace.jpg

SOU1516_4-05_Coach_House_frontage.jpg

SOU1516_4-06_Coach_House_from_corner.jpg

SOU1516_4-07_detail_of_double_door.jpg

SOU1516_4-08_room_A_and_blocked_doorway_to_pub.jpg

SOU1516_4-09_blocked_access_to_pub_in_room_C.jpg

SOU1516_4-10_from_room_A_into_room_C.jpg

SOU1516_4-11_double_door_in_room_A_from_room_C.jpg

SOU1516_4-12_room_C_from_room_B.jpg

SOU1516_4-13_room_B_NE.jpg

SOU1516_4-14_room_B_from_room_C.jpg

SOU1516_4-15_room_B_SW.jpg

SOU1516_4-16_room_A.jpg

SOU1516_4-17_staircase_in_room_B.jpg

SOU1516_4-18_room_D_NW.jpg

SOU1516_4-19_room_D_SE.jpg

SOU1516_4-20_room_D_NE.jpg

SOU1516_4-21_detail_of_staircase_scar_room_A.jpg

SOU1516_4-22_detail_of_engineering_brick_floor_and_circular_drain_in_room_A.jpg

SOU1516_4-23_detail_of_engineering_brick_floor_and_gutter_in_room_B.jpg

SOU1516_4-24_detail_of_external_drain_in_room_C.jpg

SOU1516_4-25_detail_of_wooden_hatch_R_in_room_B.jpg

SOU1516_4-26_detail_of_wooden_hatch_L_in_room_B.jpg

SOU1516_4-27_detail_of_ceiling_staircase_and_stud_wall_in_room_B.jpg

SOU1516_4-28_detail_of_ceiling_above_double_door_in_room_A.jpg

SOU1516_4-29_detail_of_dormer_window_roof_in_room_D.jpg

SOU1516_4-30_detail_of_side_of_dormer_window,_room_D.jpg
SOU1516_4-31_detail_of_roof_panel_SE_of_room_D.jpg
SOU1516_4-32_detail_of_roof_panel_NW_of_room_D.jpg
SOU1516_4-33_detail_of_water_tank_in_room_D.jpg
SOU1516_4-34_detail_of_removed_staircase_in_room_D.jpg
SOU1516_4-35_detail_of_base_of_dormer_window_in_room_D.jpg
SOU1516_4-36_detail_of_hatches_in_room_D.jpg
SOU1516_4-37_detail_of_dormer_window.jpg
SOU1516_4-38_detail_of_rebuilt_external_wall.jpg
SOU1516_4-39_scar_of_staircase_in_room_A.jpg
SOU1516_4-40_painted_wall_with_timber_course_in_room_A.jpg
SOU1516_4-41_drain_excavation_in_room_C.jpg
SOU1516_4-42_dormer_window_in_room_D.jpg
SOU1516_4-43_detail_of_small_window_in_room_D.jpg
SOU1516_4-44_detail_of_junction_of_roof_timbers_in_room_D.jpg
SOU1516_4-45_boundary_wall.jpg