

DB 11/2/8 [REDACTED]

Cow Tag 11/4 Function Code 524.24

Brief Description: [timber element, p/s, condition, fragments]
Foreman HALF of S24.2, lower edge eroded,
cut prior to clearing (from 115)

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos


- 1. B. line c. 20cm from top edge
 - " c. 20cm from top edge, lower edge
 - " ? c. 40cm from top edge, next to area of damage
 - " c. 70cm from top edge centre stain
- TYPE (7+3)

O.S :- Surface v. smooth, continuous, hard, softwood
Soft.
- POSSIBLE BORER DAMAGE

PART OF AFT END IS SAWN OFF, REST IS BROKEN OFF

Wood Science: [rings, ARW, knots, sapwood, conversion]

c 60H Radial Pith beyond
upper edge on opposite side
ARW = 215/60.



Recommended action: [samples, additional photos, moulding, queries and problems]

CALIBRATION WAS NOT PERFECT ON OUTBD. FACE (X-Y-DEVIATION OF 0.5-07); DIMENSIONS OF DRAWING SEEM TO BE OK

Cleaned: 30/08/06 BJ EC	Recorded: 31.08.06 AK	Photos:
Checked: [corrections needed]	Initials & Date: NN 17/10/06	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	