



DB 19/11/09

Cow Tag 124	Function Code 516.2B	
Brief Description: [timber element, p/s, condition, fragments] Damaged on both ends. Sapwood clearly defined on upper edge.		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos Inboard: Additional nails on aft scarf. Inscribed lines to centre of plank. Outboard: A number of inscribed lines. Large abundance of borers. Inboard: sample 25kg = from rim of land → plant material outboard: - type 2 lines (?) grouped around 5th tree nail - type 2 lines - additional nail next to 4th tree nail - deep axe mark further comment: P.T.O		
Wood Science: [rings, ARW, knots, sapwood, conversion] Radial. c 75H + 10S P.A. beyond lower edge. ARW = 222/85		
Recommended action: [samples, additional photos, moulding, queries and problems] DBMD? re-recorded ends ms 17/10/07		
Cleaned: VT/EV/EC 30/9/06	Recorded: DV 1/09/06	Photos:
Checked: [corrections needed] ✓		Initials & Date: NN 18/10/06
Corrections Done [desktop, Faro Arm?]:		Initials & Date:

DP 11/11/03



line ends here, doesn't connect up to lower edge of planks