





DB 11/2/18

Cow Tag 137	Function Code S 17.1	
Brief Description: [timber element, p/s, condition, fragments] TRUNCATED PLANK - FORE SCARP MISSING, WOOD SURFACES VERY SOFT		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos INBOARD: - TYPE 1 LINES ON AFT SCARP TYPE 1 LINES FORE OF COWTAG Outboard: degraded INBOARD: type 1 lines; additional nail angle not with 15 cm rod outboard: 3RD complete upper nail  does have nail head but no clear boundaries of this nail head. Same goes for 10th nail hole (next to 6th treenail) Forward end cut in antiquity.		
Wood Science: [rings, ARW, knots, sapwood, conversion] Radial - 120HT 2S. Pith beyond upper edge. ARW = 205/122		
Recommended action: [samples, additional photos, moulding, queries and problems] photo: possible clamp mark, inboard, forward end between 2nd & 3rd treenail		
Cleaned: 13/7/06 BS VT	Recorded: 17/07/06 D.V.	Photos:
Checked: [corrections needed] ✓		Initials & Date: NN 18/10/6
Corrections Done [desktop, Faro Arm?]:		Initials & Date:

- cut in antiquity



137 S17_1 Yardeni Vorst 17 July 2006