




12/2/8

t6

| | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Cow Tag 178 | | Function Code P8-3 |
| Brief Description: [timber element, p/s, condition, fragments] <i>Complete plank. Split damage at aft scarf</i> | | |
| Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <i>Has repair along lower edge</i> <i>Type 1 Inscribed line?</i> <i>Old control points recorded and removed.</i> <i>Need to add wood fastener centres layer</i> | | |
| Wood Science: [rings, ARW, knots, sapwood, conversion] <i>Radial at aft scarf. Pith beyond lower edge. c70HP⁵. Distinct growth band later. ARW = 230/75</i> | |  |
| Recommended action: [samples, additional photos, moulding, queries and problems] <i>Plus repair</i> | | |
| Cleaned: | ReRecorded TNJ 19.10.06 Recorded: <i>Date?</i> <i>HPM, TNJ, MMR, AMK</i> | Photos: <i>VT</i> <i>26/10/06</i> |
| Checked: [corrections needed] | | Initials & Date: |
| Corrections Done [desktop, Faro Arm?]: | | Initials & Date: |



change layer
- add new?

needs clearing out

need to
define step in scarf