


DB 12/2/8

Cow Tag 205	Function Code P5.2	
<p>Brief Description: [timber element, p/s, condition, fragments]          PORTSIDE PLANK IN GOOD CONDITION APART FROM MIDDLE, WHICH HAS BEEN SEVERELY DAMAGED BY CONCRETE PILE (NEARLY BROKEN OFF - THEREFORE PLANK AT ANGLE)</p>		
<p>Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos</p> <p>IB: SCRIBED LINES 0.20M AFT OF FORWARD EDGE, 0.38M AFT OF FORWARD EDGE AN ADDITIONAL NAIL, <sup>IT GOES THROUGH PLANK</sup> WOODEN PEG 0.88M AFT OF FORWARD EDGE</p> <p>OB: DOUBLE WOODEN NAILS, ONE OF THEM WITH DIMPLE 0.6 M forward of aft edge.</p> <p>Type 3 ◊ (I can only see &lt;!) IB forward,</p>		
<p>Wood Science: [rings, ARW, knots, sapwood, conversion]          c 90 H. P.A. beyond lower edge          Radial ARW = 183/90</p>		
<p>Recommended action: [samples, additional photos, moulding, queries and problems]</p>		
<p>Cleaned: 19/04/06 MS, LB</p>	<p>Recorded: 16/06/2006 DV</p>	<p>Photos:</p>
<p>Checked: [corrections needed] ✓</p>	<p>Initials &amp; Date: NN 21/6/6,</p>	
<p>Corrections Done [desktop, Faro Arm?]:</p>	<p>Initials &amp; Date:</p>	