


t4

DB

5/3/2008

Cow Tag <u>467</u>	Function Code <u>515.5</u>	
Brief Description: [timber element, p/s, condition, fragments] <u>Plank in good condition</u>		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <u>outboard - possible wedge in 5th → didn't see, but there is one in the 6th</u> <u>Inboard - Type 3 lines on SCARF just AFT OF FORW END</u> <u>Type 1 lines (3x) ✓</u> <u>tool marks on LAND</u> <ul style="list-style-type: none"> - POSSIBLE CLAMP MARK, INBD. - UPPER EDGE OF PLANK IS COMPRESSED / DEFORMED BY ROVES - UNUSUAL MARKS ON OUTBD. FACE (POSSIBLY FROM CLEANING? - NOT RECORDED) - POSSIBLE BORER DAMAGE, OUTBD. LOWER EDGE, CA. CENTRE OF PLANK 		
Wood Science: [rings, ARW, knots, sapwood, conversion] <u>Pith beyond base upper edge. Roded</u> <u>c 75H + 58 at aft scarf.</u> <u>ARW - 222/80</u>		
Recommended action: [samples, additional photos, moulding, queries and problems] <u>Photos of clamp mark.</u>  <u>Also Type 1 lines white at it +</u>		
Cleared: <u>27/6/06</u> <u>ms VT</u>	Recorded: <u>28 JUNE 2006 AK</u>	Photos: <u>VT</u> <u>26/10/06</u>
Checked: [corrections needed]		Initials & Date:
Corrections Done [desktop, Faro Arm?]:		Initials & Date:

tags reward VT Rel/10/06

these rings are too faded

very faded

h3p

