


DB 5/5/2008

Cow Tag 469	Function Code J 11.1
Brief Description: [timber element, p/s, condition, fragments] GOOD CONDITION PLANK TRUNCATED AT FORE END	
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos IN/BOARDS:- LOTS OF ADDITIONAL NAILS ENCAPSULATED BRANCH ✓ TOOLMARKS ON AFT SCARF - tool signatures TOOLMARKS ON LOWER EDGE OF PLANK Additional nails in centre of plank of uncertain function. Outboard. Saw marks next to tree uoc 1 st - 2 nd from fore end. — NO.	
Wood Science: [rings, ARW, knots, sapwood, conversion] Truncated sidebranch inboard = shedding Pith beyond lower edge. Radial at aft scarf. 65H ARW = 198/65	
Recommended action: [samples, additional photos, moulding, queries and problems]	
Cleaned: BJ/VT 20/06/06	Recorded: 21/06/06 MNR
Checked: [corrections needed] ✓	Photos: Initials & Date: MN 11/7/1
Corrections Done [desktop, Faro Arm?]:	Initials & Date:



469 S11_1 Monika Maleszka-Ritchie 21 June 2006
Sampans

