



DB 5/3/2008

Cow Tag 473	Function Code 514.1	
Brief Description: [timber element, p/s, condition, fragments] TRUNCATED AT FORE END, GOOD CONDITION, LARGE CRACKS		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos INBOARD: - TOOL MARKS FOR OF FUNCTION CODE CARBET Apparent type 1 on inboard face of aft scarf. OUTBOARD: - NO DEFINITE MARKS POSSIBLE LINES C. 60 cm FORE OF AFT EDGE, MIDDLE OF PLANK Cut in ambiguity along forward face of frame		
Wood Science: [rings, ARW, knots, sapwood, conversion] 2 nr horizontal knots, frequent tears Possible ore sapwood along lower edge ie pits beyond upper edge. c 65 H. ARW = 200/65. Radial at scarf.		
Recommended action: [samples, additional photos, moulding, queries and problems] - Very faint inscribed lines (horizontal) on outboard face near branch. - Some relatively "deep" axe - marks on inboard face.		
Cleaned: BS 22/06/06	Recorded: DU 26/06/06	Photos:
Checked: [corrections needed] ✓	Initials & Date: NN 11/7/06	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	

cut in anticipation (along ground face of frame)

split Rebar



473 S14_1 Yardeni Vorst 26 June 2006

