



DB 25/3/2008

Cow Tag		Function Code
475		S 12-3A
Brief Description: [timber element, p/s, condition, fragments]		
TRUNCATED PLANK - AFT SCARP MISSING		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos		
INBOARD:- POSS. TYPE 1 LINES AFT OF FUNCTION CODE LABEL & "F 14.0 OUT" LABEL		
OUTBOARD:- N.N.F. NA recorded (IB)		
Clear lower damage at lower end in at least 2 locations. Bore hole up to 9mm diameter.		
Wood Science: [rings, ARW, knots, sapwood, conversion]		
Radial - possibly some methoded sapwood 208/120. Pith beyond lower edge.		
Recommended action: [samples, additional photos, moulding, queries and problems]		
DEND - INC SAPWOOD?		
Cleaned:	Recorded:	Photos:
35 11/07/06 VT	12/07/06 MMR	
Checked: [corrections needed]	Initials & Date:	
✓	27/7/06	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	



Possible
measured
structures.

cleared pass through timber,

1 change

475 S12_3A Monika Maleszka-Ritchie 12 July 2006

