



Plate 5 The blocked gallery doorway, showing infilling at bottom and floor-joist sockets blocked with bricks to right, looking northwest.



Plate 6 The blocked gallery doorway visible above the lean-to roof, looking south.