



0009

Shot of the S side of the bayed building showing the blocked entrances. View NE



0009

Shot of the early stonework at the N end of the W wall of the byre. View E



0063

Shot of the S end of the E wall of the byre showing circular sawn stonework. View W



0066

General shot of the E side of the area to be demolished. View NW



0067

General shot showing the milk processing building and the bayed building. View NE



0026

View of the blocked southern doorway in the W wall of the byre. View NE



0046

View of the S wall of the byre from inside the bayed building. View N



0114

Shot of the northern blocked doorway in the E wall of the byre. View SW