


Direction  
of North  
taken from  
**'CASTLEHILLFARMTOP'**

### NOTES


1. THIS DRAWING IS BASED UPON DRAWING 'CASTLEHILLFARMTOP' PROVIDED BY THE CLIENT.
2. THIS DRAWING DOES NOT PROVIDE AN EXACT REPRESENTATION OF THE SUB-SURFACE. IT MUST BE USED IN CONJUNCTION WITH THE ACCOMPANYING REPORT AND IN CONjunction WITH THE INFORMATION PROVIDED IN THAT REPORT WHICH USES THE SAME TECHNIQUES EMPLOYED AND THEIR INHERENT LIMITATIONS.
3. THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS ISSUED IN CONFIDENCE AND IS THE PROPERTY OF THE CONTRACTOR. DISCLOSURE OF THIS INFORMATION TO THIRD PARTIES, UNAUTHORISED COPYING OR REPRODUCTION OF THIS DATA WITHOUT APPROVAL IS FORBIDDEN.

ALWAYS EXERCISE CAUTION WHEN EXCAVATING

### SUB-SURFACE KEY

	EXTENT OF GRADIMETER SURVEY
	AREA OF INTENSE DIPOLE MAGNETIC ANOMALIES - FERROUS CONTAMINATION
	AREA OF VARYING INTENSITY DIPOLE MAGNETIC ANOMALIES - INDICATIVE OF DEPOSITS CONTAINING IRON/OXIDE RUSTABLE METALS SUCH AS BUILDING RUIN

AREA OF VARYING INTENSITY DIPOLE MAGNETIC ANOMALIES - INDICATIVE OF DEPOSITS CONTAINING IRON/OXIDE RUSTABLE METALS SUCH AS BUILDING RUIN



30000

50000

40000

40000

50000

30000

20000

10000

0