# Standing Building Survey Achath Farm steading, garage and bothy Castle Fraser, Kemnay, AB51 7LJ







Alison Cameron Cameron Archaeology 4 November 2013

# **Standing Building Survey**

INTRODUCTION

#### **CONTENTS**


1 INTRODUCTION	3
2 THE STANDING BUILDING SURVEY	4
2.1 BUILDING 1	4
2.2 BUILDING 2	9
2.3 BUILDING 3	9
3 REFERENCES	. 11
4 ACKNOWLEDGEMENTS	. 11
APPENDIX 1 PHOTOGRAPHS	. 12
ILLUSTRATIONS	
ILLUSTRATIONS	
Illus 1 Location plan  Illus 2 Plan of Building 1 showing all blocked doors and windows and new apertures  Illus 3 Building 1 west wing (right) showing bell-cote and void for armorial panel  Illus 4 Building 1 west wing bellcote and void for armorial panel; facing south  Illus 5 Elevations of Building 2	4 5 6 7 7 8 9 . 10 . 10 . 11 . 12

# **SUMMARY**

A Level 2 standing building survey was carried out on a steading as there is a planning application for conversion (Aberdeenshire Council planning application 2013/2674). This report also includes photographic surveys of the garage and bothy (2013/1751 and 1753). It is recommended that no further archaeological work is required at this site during the current development.

#### 1 INTRODUCTION

The site is in Cluny parish, the NGR for the farm is NJ73174 10960 and it lies at 155-160m OD. The work was commissioned by Kenny Stuart, E H New Forest Ltd, Brathens ECO Business Park, Hill of Brathens, Banchory, AB31 4BW and is in response to Aberdeenshire Council planning application 2013/2674 for conversion of steadings to form dwellinghouses. There is a requirement for a Level 2 standing building survey. This report also includes photographic surveys of the garage and bothy (2013/1751 and 1753).



Illus 1 Location plan (Contains Ordnance Survey data © Crown copyright and database right 2013).


Roy's map of 1747-55 (Illus 15) shows 'Adhatt' as a small group of buildings, presumably Achath but this site is not named on any earlier maps (Gordon, Blaeu). The buildings appear in their current form on the First and Second Edition OS maps (Illus 12-13).

#### 2 THE STANDING BUILDING SURVEY

The standing building survey took place on 31 October 2013; the weather was intermittently sunny, cold and cloudy. Achath farmhouse dates to c1800 (NJ71SW 30; Shepherd 2006, 151-2) and is listed B. The steading is probably contemporary with the house and the garage and bothy appear to be slightly later, probably mid-19th century. Achath was part of the Castle Fraser Estate. The elaborate stables at Castle Fraser date to 1795; they are constructed of similar materials to Achath but with circular angle-towers (ibid, 152).

#### 2.1 BUILDING 1

Building 1 is a C-shaped steading with a central courtyard (Illus 2). The buildings are constructed of large blocks of grey and pink granite with cherry cocking and are 30m N-S and 33m E-W. The complex has an east, north and west wing and a narrow entrance 3m wide in the south wing to access the courtyard and this was built in one phase.



Illus 2 Plan of Building 1 showing all blocked doors and windows and new apertures (copyright EH New Forest)




Illus 3 Building 1 west wing (right) showing bell-cote and void for armorial panel; facing SE



Illus 4 Building 1 west wing bellcote and void for armorial panel; facing south

Above the north gable of the west wing are a bellcote and a void which would have held an armorial panel (Illus 3, 4). The bellcote is constructed of sandstone and was probably for a single bell. The void for the armorial panel is a pointed arch; the panel was probably made of marble or sandstone and may have been removed when the owners moved or sold the property.



Illus 5 Elevations of Building 2 (copyright EH New Forest)

Building 1 was converted for use as a piggery and as a result there are no internal fittings or architectural details visible. A series of original doors and windows have been blocked and new apertures created including large doors in the SE wing (Illus 5). A separate building (seen on the Second Edition OS map; Illus 12) was recently removed from the exterior of the north wall and evidence of this can be seen on this wall (Illus 3).



Illus 6 South elevation showing entrance into courtyard; facing north



Illus 7 North gable of east wing showing original cart door with granite arched top



Illus 8 Cart doors on the west elevation; facing east



Illus 9 North end of west elevation showing repairs to wall following removal of horse mill; facing east

The First and Second Ordnance Survey maps (Illus 12, 13) show a horse mill attached to the west side of the west wing adjacent to the bell-cote. This building does not survive but there is evidence on the wall that repairs have taken place, probably after the removal of this mill (Illus 9). The mill was probably used for threshing.

The south half of the west wing has three cart doors (now blocked; Illus 8) which are of the same construction as the cart door at the north end of the east wing (Illus 7); the arches of these door are constructed from dressed granite blocks forming a flat-topped arch.

#### 2.2 BUILDING 2




Illus 10 Building 2 used latterly as a garage; facing NNE


#### 2.3 BUILDING 3



Illus 11 Building 3 facing SW



Illus 12 First Edition Ordnance Survey (copyright National Library of Scotland) Aberdeen Sheet LXIV.14 (Cluny) Survey date: 1864 Publication date: 1869



Illus 13 Second Edition Ordnance Survey (*copyright National Library of Scotland*) Aberdeenshire, Sheet 064.14 Publication date: 1900 Revised: ca. 1899

### 3 REFERENCES


Shepherd, IAS 2006 'Aberdeenshire: Donside and Strathbogie - An Illustrated Architectural Guide', 151-2,

#### 4 ACKNOWLEDGEMENTS

Thanks to Claire Herbert at Aberdeenshire Archaeology Service and to staff at EH New Forest.

Cameron Archaeology
45 View Terrace
Aberdeen
AB25 2RS
01224 643020
07581 181057
cameronarch@btinternet.com
www.cameronarchaeology.com
Company registration no 372223 (Scotland)
VAT registration no 990 4373 00

# **APPENDIX 1 PHOTOGRAPHS**



Illus 14 Camera points used in this standing building survey

Photo no	Description	Facing	Camera point
DSC_7769-7774	Building 2: garage SW facade with inserted garage door	NE	1
DSC_7775-7780	Building 2: garage SE facade with original doors and windows	N	2
DSC_7781-7786	Building 2: garage blocked door	NW	3
DSC_7787-7792	Building 2: garage SE facade with original doors and windows	NW	4
DSC_7793-7798	Building 2: garage blocked door	NW	5
DSC_7799-7804	Building 2: garage and Building 1 behind	SW	6
DSC_7805-7810	Building 2: garage	SW	7
DSC_7811-7817	Building 2: garage NE wall	SW	8


	D. Helion 2. Toward NIM hards well about the contract of the c		
DSC_7818-7823	Building 2: garage NW back wall showing overgrown vegetation	SE	9
DSC 7824-7829	Building 1: main steading north facade	SW	10
	Building 1: main steading north gable east wing with cart door		
DSC_7830-7835	and original window above	S	11
DSC 7836-7846	Building 1: main steading north gable east wing cart door	S	11
DSC 7847-7853	Building 1: main steading interiors all converted for piggery		12
	Building 1: main steading north gable east wing cart door		
DSC_7854-7860	original door fittings	SW	13
	Building 1: main steading north facade - there was a modern		
	building attached to this facade which was recently		
DSC_7861-7866	demolished	SSW	11
DSC_7867-7878	Building 2: garage interiors		14
	Building 1: main steading west wing north gable with bell-		
DSC_7879-7897	cote and void for armorial panel	S	15
	Building 1: main steading west wing north gable with bell-		
DSC_7898-7909	cote and void for armorial panel	SW	16
DSC 7040 7044	Building 1: main steading (right) with house (not included in	_	4.6
DSC_7910-7914	this survey, left)	E	16
	Building 1: main steading west wing north gable with bell-		
DSC_7915-7919	cote and void for armorial panel	S	15
DSC_7920-7921	Building 1: main steading west wing interiors converted for	S	17
DSC_7920-7921 DSC_7922-7933	piggery   Building 1: main steading west wing north end bell-cote	E	18
DSC_7922-7933	Building 1: main steading west wing north end bell-cote	NE	18
<del>-</del>		E	18
DSC_7943-7954	Building 1: main steading west wing north end bell-cote	Е	18
DCC 70FF 7060	Building 1: main steading west wing west wall showing possible scar from horse mill	E	19
DSC_7955-7960	<del>  `                                   </del>		_
DSC_7961-7966	Building 1: main steading	SE	20
DSC_7967-7972	Building 1: main steading west wing	ESE	21
DCC 7072 7070	Building 1: main steading west wing west wall showing	_	22
DSC_7973-7978	possible scar from horse mill	E	22
DCC 7070 7004	Building 1: main steading west wing west wall showing		22
DSC_7979-7984	possible scar from horse mill	E E	23
DSC_7985-7991	Building 1: main steading northern cart door	E	24
DSC_7992-8004	Building 1: main steading west wing cart doors		25
DSC_8005-8016	Building 1: main steading west wing	NE	26
DSC_8017-8022	Building 1: main steading west wing cart doors	E	25
DSC_8023-8028	Building 1: main steading west wing	NE	26
DSC_8029-8034	Building 1: main steading west wing (left) and Building 3 (right)	E	26
DSC_8035-8040	Building 1: main steading SW wing	N	27
D3C_0033-0040	Building 1: main steading SW wing  Building 1: main steading SW wing south wall blocked door	IV	21
DSC 8041-8046	and windows	N	28
_ :	Building 1: main steading SW wing south wall blocked door		-
DSC_8047-8052	and windows	N	29
	Building 1: main steading SW wing south wall blocked		
DSC_8053-8058	window	N	30


DSC_8064-8069 wi DSC_8070-8074 Bu DSC_8075-8080 co DSC_8081-8086 Bu DSC_8087-8091 Bu DSC_8092-8097 Bu DSC_8098-8103 de DSC_8111-8116 Bu DSC_8117-8122 co DSC_8123-8126 Bu	uilding 1: main steading SW wing south wall blocked door uilding 1: main steading SW wing south wall blocked indow uilding 1: main steading entrance to courtyard uilding 1: main steading SW wing rounded corner into ourtyard uilding 1: main steading SW wing blocked door uilding 1: main steading SW wing north wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing south wall in courtyard uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in courtyard uilding 1: main steading south east wing north wall in courtyard uilding 1: main steading south east wing north wall in courtyard	N N N N W S W W R E	31 32 33 34 35 36 37 38 39 39
DSC_8064-8069 wi DSC_8070-8074 Bu Bu DSC_8075-8080 co DSC_8081-8086 Bu DSC_8087-8091 Bu DSC_8092-8097 Bu Bu DSC_8098-8103 de DSC_8104-8110 Bu DSC_8111-8116 Bu DSC_8117-8122 co DSC_8123-8126 Bu	uilding 1: main steading entrance to courtyard uilding 1: main steading SW wing rounded corner into burtyard uilding 1: main steading SW wing blocked door uilding 1: main steading SW wing north wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard etail of blocked doors uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in burtyard	N NW W S W W	33 34 35 36 37 38 39
DSC_8070-8074 Bu  DSC_8075-8080 co  DSC_8081-8086 Bu  DSC_8087-8091 Bu  DSC_8092-8097 Bu  DSC_8098-8103 de  DSC_8104-8110 Bu  DSC_8111-8116 Bu  DSC_8117-8122 co  DSC_8123-8126 Bu	uilding 1: main steading SW wing rounded corner into ourtyard uilding 1: main steading SW wing rounded corner into ourtyard uilding 1: main steading SW wing blocked door uilding 1: main steading SW wing north wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in uurtyard	N NW W S W W	33 34 35 36 37 38 39
DSC_8075-8080 co  DSC_8081-8086 Bu  DSC_8087-8091 Bu  DSC_8092-8097 Bu  DSC_8098-8103 de  DSC_8104-8110 Bu  DSC_8111-8116 Bu  DSC_8117-8122 co  DSC_8123-8126 Bu	uilding 1: main steading SW wing rounded corner into purtyard uilding 1: main steading SW wing blocked door uilding 1: main steading SW wing north wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard etail of blocked doors uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in purtyard	NW W S W W	34 35 36 37 38 39
DSC_8075-8080 co DSC_8081-8086 Bu DSC_8087-8091 Bu DSC_8092-8097 Bu DSC_8098-8103 de DSC_8104-8110 Bu DSC_8111-8116 Bu DSC_8117-8122 co DSC_8123-8126 Bu	purtyard uilding 1: main steading SW wing blocked door uilding 1: main steading SW wing north wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in uurtyard	W S W W N E	35 36 37 38 39
DSC_8081-8086 Bu DSC_8087-8091 Bu DSC_8092-8097 Bu DSC_8098-8103 de DSC_8104-8110 Bu DSC_8111-8116 Bu DSC_8117-8122 co DSC_8123-8126 Bu	uilding 1: main steading SW wing blocked door uilding 1: main steading SW wing north wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard etail of blocked doors uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in ourtyard	W S W W N E	35 36 37 38 39
DSC_8087-8091 Bu  DSC_8092-8097 Bu  DSC_8098-8103 de  DSC_8104-8110 Bu  DSC_8111-8116 Bu  DSC_8117-8122 co  DSC_8123-8126 Bu	uilding 1: main steading SW wing north wall in courtyard uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard etail of blocked doors uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in courtyard	S W W N E	36 37 38 39
DSC_8092-8097 Bu  DSC_8098-8103 de  DSC_8104-8110 Bu  DSC_8111-8116 Bu  DSC_8117-8122 co  DSC_8123-8126 Bu	uilding 1: main steading west wing east wall in courtyard uilding 1: main steading west wing east wall in courtyard etail of blocked doors uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in courtyard	W W N E	37 38 39
DSC_8098-8103 de DSC_8104-8110 Bu DSC_8111-8116 Bu DSC_8117-8122 co DSC_8123-8126 Bu	uilding 1: main steading west wing east wall in courtyard etail of blocked doors uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in courtyard	W N E	38 39
DSC_8098-8103 de DSC_8104-8110 Bu DSC_8111-8116 Bu DSC_8117-8122 co DSC_8123-8126 Bu	etail of blocked doors  uilding 1: main steading north wing south wall in courtyard  uilding 1: main steading east wing west wall in courtyard  uilding 1: main steading south east wing north wall in  burtyard	N E	39
DSC_8104-8110 Bu  DSC_8111-8116 Bu  Bu  DSC_8117-8122 co  DSC_8123-8126 Bu	uilding 1: main steading north wing south wall in courtyard uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in burtyard	N E	39
DSC_8111-8116 Bu  Bu  DSC_8117-8122 co  DSC_8123-8126 Bu	uilding 1: main steading east wing west wall in courtyard uilding 1: main steading south east wing north wall in burtyard	Е	
DSC_8117-8122 co DSC_8123-8126 Bu	uilding 1: main steading south east wing north wall in ourtyard		39
DSC_8117-8122 co DSC_8123-8126 Bu	purtyard	ς	
DSC_8123-8126 Bu	·		40
	uilding 1: main steading exit from courtyard	S	41
-55_512, 5130   Du	uilding 1: main steading exit nom courtyard	SE	41
DSC 8139-8143 Bu	uilding 1: main steading SE wing south facade	N	42
_	uilding 1: main steading SE wing south facade	N	43
	uilding 1: main steading SE wing south facade	N	44
_	uilding 1: main steading SE wing south racade	IN	<del> </del>
	ggery	N/W	45
	uilding 1: main steading SE wing	NW	46
	uilding 1: main steading east wing east wall	W	47
	uilding 1: main steading east wing east wall	W	48
	uilding 1: main steading east wing east wall	W	49
DSC_8180-8186 Bu	uilding 1: main steading east wing east wall	W	50
DSC_8187-8192 Bu	uilding 1: main steading east wing east wall	W	51
DSC_8195-8200 Bu	uilding 1: main steading east wing	SW	10
DSC_8201-8206 Bu	uilding 1: main steading west wing	SE	20
DSC_8207-8212 Bu	uilding 1: main steading west wing bell-cote on north wall	ESE	52
DSC_8213-8217 Bu	uilding 3	SE	53
DSC_8218-8229 Bu	uilding 3 north facade	S	33
DSC_8230-8235 Bu	uilding 3 north facade door	S	54
DSC_8236-8241 Bu	uilding 3 north facade cart door	S	55
DSC_8242-8247 Bu	uilding 3	SW	42
	uilding 3	W	56
DSC_8254-8256 Bu	uilding 3 east room interior	S	57
DSC_8259 Bu	uilding 3 east room interior	SE	57
_	uilding 3 west room interior converted and panelled	S/SE	58
	uilding 3	NE	59
	uilding 3	N	60
	uilding 3	Е	61
_	uilding 1 west wing north wall bell-cote	NE	18
	uilding 1 west wing west wall and bell-cote	E	18

DSC_8296-8310	Building 1 west wing west wall showing scars where horse mill may have been attached	E	19
DSC_8311-8315	Building 1 west wing west wall showing scars where horse mill may have been attached	E	18
DSC_8316-8320	Building 1 bell-cote	Е	52
DSC_8321-8322	Building 1 bell-cote	S	15
DSC_8323-8328	Building 1 bell-cote	WSW	16









Illus 15 Roy 1747-55 showing 'Castle Frazer', Brenill (now Braeneil) and 'Adhatt' presumably now Achath (copyright National Library of Scotland).