


**SITE AT EAST AUCHREDDIE FARMHOUSE,
ELLON, AB41 8PH
PHOTOGRAPHIC SURVEY
FOR ABERDEENSHIRE PLANNING APPLICATION
APP/2013/2013
NJ 91757 34868**



**Alison Cameron
Cameron Archaeology
11.3.2014**



Plan showing camera points used in this survey



DSC_1628



DSC_1637



DSC_1638



DSC_1647



DSC_1648



DSC_1649



DSC_1650



DSC_1651



DSC_1652



DSC_1653



DSC_1654



DSC_1655



DSC_1656



DSC_1659



DSC_1660



DSC_1662



DSC_1663



DSC_1664



DSC_1665



DSC_1666



DSC_1667



DSC_1679



DSC_1680



DSC_1695



DSC_1696



DSC_1710



DSC_1711



DSC_1712



DSC_1713



DSC_1714



DSC_1715



DSC_1716



DSC_1717



DSC_1718



DSC_1719



DSC_1720



DSC_1721



DSC_1722



DSC_1723



DSC_1724



DSC_1725



DSC_1726



DSC_1727



DSC_1728



DSC_1729



DSC_1738



DSC_1739




DSC_1744



DSC_1753



DSC_1754



DSC_1755



DSC_1762



DSC_1765



DSC_1772



DSC_1773



DSC_1780



DSC_1790



DSC_1791



DSC_1796



DSC_1803



DSC_1815



DSC_1826



DSC_1827



DSC_1835



DSC_1836



DSC_1837



DSC_1838



DSC_1841



DSC_1850



DSC_1851

Photo no	Description	Facing	Camera point
DSC_1628-1632	Steading block A south face	N	1

DSC_1633-1637	Steading block A south face west end	N	2
DSC_1638-1642	Steading block A south face centre	N	3
DSC_1643-1647	Steading block A south face east end	N	4
DSC_1648	Steading block A interior south wall east end	S	5
DSC_1649	Steading block A interior east gable	E	5
DSC_1650	Steading block A interior north wall	N	5
DSC_1651	Steading block A interior	NE	5
DSC_1652	Steading block A interior wall thickness and construction in doorway in south wall	W	6
DSC_1653	Steading block A interior wall thickness and construction in doorway in south wall	E	6
DSC_1654	Steading block A interior NW corner	NW	7
DSC_1655-59	Steading block A interior west gable with fireplace	W	7
DSC_1660-62	Steading block A interior SW corner	SW	7
DSC_1663-64	Steading block A interior window in south wall west of door	S	8
DSC_1665	Steading block A interior SW corner	SW	7
DSC_1666	Steading block A interior south wall west of door	S	8
DSC_1667-72	Block A west gable	E	9
DSC_1673-79	Block A	NE	10
DSC_1680-95	Block A north wall	SSW	11
DSC_1696-1705	Block B south wall	N	12
DSC_1706-10	Block B south wall door in east end	N	14
DSC_1711-12	Block B interior south wall east door	SW	16
DSC_1713	Block B interior south wall east door	SE	15
DSC_1714	Block B interior south wall east door	S	16
DSC_1715	Block B interior east gable	E	16
DSC_1716-17	Block B interior north wall east end	N	16
DSC_1718-19	Block B interior wooden partition	W	16
DSC_1720	Block B interior wooden partition	E	18

DSC_1721	Block B interior north wall east end	N	18
DSC_1722	Block B interior west wall	W	18
DSC_1723	Block B interior west wall	W	16
DSC_1724-25	Block B interior west room door in south wall	S	18
DSC_1726-27	Block B interior west room door in south wall	S	18
DSC_1728	Block B interior west room wall east of door in south wall	SE	18
DSC_1729-33	Block B south wall centre between doors	N	3
DSC_1734-38	Block B south wall west door	N	19
DSC_1739-43	Block B south wall west end	N	20
DSC_1744-48	Block B south wall	ENE	21
DSC_1749-57	Block B west extension (now used as garage) west gable	E	22
DSC_1758-63	Block B west extension (now used as garage) west gable	E	23
DSC_1764-68	Block B north wall	SSE	24
DSC_1769-72	Block B north wall	SW	25
DSC_1773-90	Block B north wall	s	25
DSC_1791-1801	Block B north wall	S	26
DSC_1802-11	Block B north wall	SW	25
DSC_1812-16	Block B north wall	S	25
DSC_1817-26	Block A east gable (right) Block B (left)	ENE	28
DSC_1827-31	Block A east gable (right) Block B (left)	ESE	33
DSC_1832-37	Block B east gable (right) Block A (left)	N	29
DSC_1838-40	Block A	N	29
DSC_1841-45	Block A east gable	W	30
DSC_1846-50	Block B east gable	W	31
DSC_1851-55	Block B east gable (right) Block A (left)	SW	32