

PITTODRIE HOUSE HOTEL, PITCAPLE, ABERDEENSHIRE, AB51 5HS

Aberdeenshire Planning Application APP/2013/3267

Listed Building Consent APP/2013/3271

NJ 69734 23985




Photo no	Description	Facing	Camera point
DSC_0171	South façade of Hotel showing location of dining room, kitchen and banquet hall extension	NNE	1
DSC_0172	South façade of Hotel showing location of dining room, kitchen and banquet hall extension	NNE	2
DSC_0173	South façade of Hotel showing location of dining room, kitchen and banquet hall extension	NW	3
DSC_0174	South window drawing room	NNE	3
DSC_0175	South façade of Hotel showing location of dining room, kitchen and banquet hall extension	NW	4
DSC_0176	South window drawing room	ESE	4
DSC_0177	South wall Old Dining Room	NNE	4
DSC_0178	South wall Old Dining Room (left) south window Drawing Room (right)	ENE	4
DSC_0179-180	South window drawing room (bottom)	NNE	4
DSC_0181-2	Turret stair at SE end of proposed extension	NNW	4
DSC_0183-4	Turret stair at SE end of proposed extension	NNE	5
DSC_0185-6	Turret stair at SE end of proposed extension	NNE	6
DSC_0187-9	Turret stair at SE end of proposed extension	ESE	8
DSC_0190-1	Turret stair at SE end of proposed extension	ESE	7
DSC_0192	Turret stair (right) south window Dining Room (left)	ENE	7
DSC_0193	South window Dining Room	NNW	7
DSC_0194	South window Dining Room	NNE	7
DSC_0195	South window Dining Room (bottom)	NNE	7
DSC_0196	South window Dining Room	NE	9
DSC_0197	South window Dining Room	NNE	8
DSC_0198	South window Dining Room	NNE	9
DSC_0199	South window Dining Room	NE	9
DSC_0200	Gable end of kitchen (left) and pantry preparation (right)	NNE	11
DSC_0201	South window Dining Room	NE	11
DSC_0202	South façade of Hotel showing location of dining room, kitchen and banquet hall extension	ENE	11
DSC_0203-4	South façade of Hotel showing location of dining room, kitchen and banquet hall extension	NE	11
DSC_0205	Pantry preparation south window	NNE	12
DSC_0206	Pantry preparation south window	NNE	13
DSC_0207	Room 1st floor above pantry prep south window	NNE	13
DSC_0208	Kitchen south window	NNE	14
DSC_0209	Room 1st floor above Kitchen south window	NNE	14
DSC_0210	Kitchen south window	NNE	15
DSC_0211	Room 1st floor above Kitchen south window	NNE	15

DSC_0212	Kitchen S wall	ENE	16
DSC_0213	Kitchen (right), food prep (middle), dining room (right)	NE	16A
DSC_0214-5	Kitchen (right), food prep (middle), dining room (right)	NNE	17
DSC_0216-7	Lounge (left) Banquet Hall (right)	NNE	18
DSC_0218	Lounge (left) Banquet Hall (right)	ENE	19
DSC_0219	Lounge (left) Banquet Hall (right)	ENE	24
DSC_0220	Kitchen (right) Banquet hall (left)	ESE	20
DSC_0221	Banquet Hall S wall windows	NNE	20
DSC_0222	Banquet Hall 1st floor above S wall windows	NNE	20
DSC_0223	Banquet Hall S wall windows	NNE	21
DSC_0224-5	Banquet Hall 1st floor above S wall windows	NNE	21
DSC_0226	Banquet Hall S wall windows	NNE	22
DSC_0227-8	Banquet Hall 1st floor above S wall windows	NNE	22
DSC_0229-30	Turret stair (now converted to a bar on interior)	NNW	22
DSC_0231-2	Turret stair (now converted to a bar on interior)	NW	22
DSC_0233-5	Turret stair (now converted to a bar on interior)	NNW	23
DSC_0236	Turret stair ground floor window	NNE	23
DSC_0237	Lounge S wall	NNE	24
DSC_0238	Lounge S wall ground floor window	NNE	25
DSC_0239	Lounge	ESE	26
DSC_0240-1	NW wing NW façade	ESE	27
DSC_0242-3	NW wing (right) turret stair (still in use) (centre)	SSE	28
DSC_0244-5	Entrance into NW wing (to be altered during proposed development)	ESE	29
DSC_0256-7	NW wing NE wall	SSW	31
DSC_0258-62	NW wing NE wall (right) turret stair (left)	SSW	30
DSC_0263	NW wing NE wall ground floor window	SSW	32
DSC_0264	NW wing NE wall ground floor window	SSW	33
DSC_0265-7	Turret stair	SSE	31
DSC_0268	Turret stair (left) NW wing (right)	SSW	33A
DSC_0269	Turret stair (left) NW wing (right)	SW	34
DSC_0270-1	NE hotel façade	SSW	34
DSC_0272	Turret stair (left) NW wing (right)	SW	34
DSC_0273-4	NE hotel façade	SSW	34
DSC_0275-6	NE hotel façade	SSW	35
DSC_0277	Turret stair external stair	W	36
DSC_0278	Turret stair external stair	SW	37
DSC_0279	Turret stair interior	SW	38
DSC_0280-85	NE hotel façade	SSW	39/40
DSC_0286	Dining Room interior	SW	41
DSC_0287	Dining Room interior	WSW	41
DSC_0288-9	Dining Room interior	WNW	42
DSC_0290-1	Dining Room S wall	SW	42

DSC_0292-7	S wall above Dining Room extension	NW/N/NNE	42
DSC_0298-9	Pantry Preparation south window interior	SW	43
DSC_0300-1	Pantry Preparation	NW	44
DSC_0302-3	Pantry Preparation	NE	44
DSC_0304-5	Pantry Preparation	WNW	43
DSC_0306-8	Kitchen	SW/W/NW	45
DSC_0309	Pantry Preparation S window	SSW	44
DSC_0310	Pantry Preparation S window	SSW	46
DSC_0311-2	Kitchen windows	WSW	47
DSC_0313-4	Kitchen	NW/W	45
DSC_0315	Corridor from NW kitchen door	SW	48
DSC_0316	Banquet Hall S window	SSW	49
DSC_0317-8	Banquet Hall	NW	49
DSC_0319-21	Banquet Hall	SW/W/WNW	50
DSC_0322-4	Banquet Hall S window	SW	51
DSC_0325-6	Banquet Hall	SE	51
DSC_0327	Turret stair (now converted to bar)	SW	51
DSC_0328	Turret stair (now converted to bar)	SW	52
DSC_0329	Turret stair (now converted to bar)	SSW	53
DSC_0330-32	Turret stair (now converted to bar)	ESE/ENE	54/55
DSC_0333	Lounge SE facing French doors	ESE	55
DSC_0334	Lounge SSW facing window	SSW	55
DSC_0336-8	Lounge SW wall	SW	54
DSC_0339-40	Lounge NW wall	NW	55
DSC_0341-2	NW wing main entrance	NW	56
DSC_0343-51	Turret stair interior	NNE/NE	57



DSC_0171.JPG



DSC_0172.JPG



DSC_0173.JPG



DSC_0174.JPG



DSC_0175.JPG



DSC_0176.JPG



DSC_0177.JPG



DSC_0178.JPG



DSC_0179.JPG



DSC_0180.JPG



DSC_0181.JPG



DSC_0182.JPG



DSC_0183.JPG



DSC_0184.JPG



DSC_0185.JPG



DSC_0186.JPG



DSC_0187.JPG



DSC_0188.JPG



DSC_0189.JPG



DSC_0190.JPG



DSC_0191.JPG



DSC_0192.JPG



DSC_0193.JPG



DSC_0194.JPG



DSC_0195.JPG



DSC_0196.JPG



DSC_0197.JPG



DSC_0198.JPG



DSC_0199.JPG



DSC_0200.JPG



DSC_0201.JPG



DSC_0202.JPG




DSC_0203.JPG



DSC_0204.JPG



DSC_0205.JPG



DSC_0206.JPG



DSC_0207.JPG



DSC_0208.JPG



DSC_0209.JPG



DSC_0210.JPG



DSC_0211.JPG



DSC_0212.JPG



DSC_0213.JPG



DSC_0214.JPG



DSC_0215.JPG



DSC_0216.JPG



DSC_0217.JPG



DSC_0218.JPG



DSC_0219.JPG



DSC_0220.JPG



DSC_0221.JPG



DSC_0222.JPG



DSC_0223.JPG



DSC_0224.JPG



DSC_0225.JPG



DSC_0226.JPG



DSC_0227.JPG



DSC_0228.JPG



DSC_0229.JPG



DSC_0230.JPG



DSC_0231.JPG



DSC_0232.JPG



DSC_0233.JPG



DSC_0234.JPG



DSC_0235.JPG



DSC_0236.JPG



DSC_0237.JPG



DSC_0238.JPG



DSC_0239.JPG



DSC_0240.JPG



DSC_0241.JPG



DSC_0242.JPG



DSC_0243.JPG



DSC_0244.JPG



DSC_0245.JPG



DSC_0256.JPG



DSC_0257.JPG



DSC_0258.JPG



DSC_0259.JPG



DSC_0260.JPG



DSC_0261.JPG



DSC_0262.JPG



DSC_0263.JPG



DSC_0264.JPG



DSC_0265.JPG



DSC_0266.JPG



DSC_0267.JPG



DSC_0268.JPG



DSC_0269.JPG



DSC_0270.JPG



DSC_0271.JPG



DSC_0272.JPG



DSC_0273.JPG



DSC_0274.JPG



DSC_0275.JPG



DSC_0276.JPG



DSC_0277.JPG



DSC_0278.JPG



DSC_0279.JPG



DSC_0280.JPG



DSC_0281.JPG



DSC_0282.JPG



DSC_0283.JPG



DSC_0284.JPG



DSC_0285.JPG



DSC_0286.JPG



DSC_0287.JPG



DSC_0288.JPG




DSC_0289.JPG



DSC_0290.JPG



DSC_0291.JPG



DSC_0292.JPG



DSC_0293.JPG



DSC_0294.JPG



DSC_0295.JPG



DSC_0296.JPG



DSC_0297.JPG



DSC_0298.JPG



DSC_0299.JPG



DSC_0300.JPG



DSC_0301.JPG



DSC_0302.JPG



DSC_0303.JPG



DSC_0304.JPG



DSC_0305.JPG



DSC_0306.JPG



DSC_0307.JPG



DSC_0308.JPG



DSC_0309.JPG



DSC_0310.JPG



DSC_0311.JPG



DSC_0312.JPG



DSC_0313.JPG



DSC_0314.JPG



DSC_0315.JPG



DSC_0316.JPG



DSC_0317.JPG



DSC_0318.JPG



DSC_0319.JPG



DSC_0320.JPG



DSC_0321.JPG



DSC_0322.JPG




DSC_0323.JPG



DSC_0324.JPG



DSC_0325.JPG



DSC_0326.JPG



DSC_0327.JPG



DSC_0328.JPG



DSC_0329.JPG



DSC_0330.JPG



DSC_0331.JPG



DSC_0332.JPG



DSC_0333.JPG



DSC_0334.JPG



DSC_0335.JPG



DSC_0336.JPG



DSC_0337.JPG



DSC_0338.JPG



DSC_0339.JPG



DSC_0340.JPG




DSC_0341.JPG



DSC_0342.JPG



DSC_0343.JPG



DSC_0344.JPG



DSC_0345.JPG



DSC_0347.JPG



DSC_0348.JPG



DSC_0349.JPG



DSC_0350.JPG



DSC_0351.JPG