


DB 7/2/8

Cow Tag 109		Function Code S 5.2A
Brief Description: [timber element, p/s, condition, fragments] GOOD CONDITION, TRUNCATED AT AFT END		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos INSIDE:- 1 LINE, VERTICAL, ACROSS MIDDLE OF PLANK C. 40cm FROM AFT END. Type 3 (←) to crack at forward end. Outboard: Dimples on tree nails.		
Wood Science: [rings, ARW, knots, sapwood, conversion] Radial - 804. Pith beyond upper edge? ARW = 185/80.		
Recommended action: [samples, additional photos, moulding, queries and problems] Thickness problem with lower forward edge of plank. Drawing is thicker than actual plank... very thin scarf. Plank 1-2 mm thick. Drawing 10 mm thick.		
Cleaned: LB/BJ/VT 30/05/06	Recorded: TNJ 14.06.06	Photos:
Checked: [corrections needed] ✓	Initials & Date: NN 14/6/6	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	