



DB 14/2/18

Cow Tag: 215		Function Code: P 13-2
Brief Description: [timber element, p/s, condition, fragments] GOOD CONDITION PLANK Unusually long		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <u>INBOARDS:-</u> ?/? - 2 SETS OF INSCRIBED LINES TYPE 1 & 2 - 3 POSSIBLE CLAMP MARKS (AFT END)		
<u>OUTBOARD:-</u> POSSIBLE LINES FOR OF 3rd TREENAIL FROM FAR END Possible wedged treenail heads		
Wood Science: [rings, ARW, knots, sapwood, conversion] Generally v straight grained but one substantial knot (+ associated loss of sapwood). Sapwood along majority of lower edge. Radial (see sketch) C125H+5S ARW = 225/130		
Recommended action: [samples, additional photos, moulding, queries and problems] - POSSIBLE BORER DAMAGE INBD. + OUTBD.		
Cleaned: AT 35 6/7/06 VT TNS	Recorded: 13.07.06 AK	Photos:
Checked: [corrections needed] ✓		Initials & Date: MN 27/7/6
Corrections Done [desktop, Faro Arm?]:		Initials & Date:



clear level



not get into the commission

2418 P412\_2 Angala Karsen 12 July 2008