



DB 19/2/08

Cow Tag 223		Function Code 54.3
Brief Description: [timber element, p/s, condition, fragments] VERY WELL PRESERVED PLANK		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos 2 PLUGGED HOLES FORW. OF AFT END (UPPER + LOWER EDGE) 1 PLUGGED HOLE FORW. OF AFT END (UPPER EDGE) 2 ADDITIONAL NAILS FORW. OF AFTEND, RIGHT NEXT TO AFT-EDGE OF PLANK ✓ 2 ADDITIONAL NAILS AFT OF FORW. END (^{found} OUTBD. SCARF) ✓ LOWER EDGE OF PLANK HAS GOT A STEP  Heavy wear upper inner edge.		
Wood Science: [rings, ARW, knots, sapwood, conversion] Radial at aft scarf c 120H ARW=225/120. Pth beyond lower edge.		
Recommended action: [samples, additional photos, moulding, queries and problems] NOTE: THE DRAWING SHOWS THE PLANK THICKER THAN IT IS, IN THE AFTER-UPPER CORNER (DRAWING - THICKNESS: 7mm; PLANK - THICKNESS: 7.5mm) ^{ACTUALLY} _{ACTUAL} - need to experiment with hand to detect this? NN.		
Cleaned: 23.03.06 AK	Recorded: 12.04.06 AK	Photos:
Checked: [corrections needed] ✓	Initials & Date: NN 26/4/6	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	