


DB 19/2/8

Cow Tag 231		Function Code P 13.6	
Brief Description: [timber element, p/s, condition, fragments] GOOD CONDITION PLANK			
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos INBOARD:- INSCRIBED 'V' IMMEDIATELY FORE OF 3rd Tree nail AFT OF FORE END, INSCRIBED 'V' IMMEDIATELY AFT OF 5th Tree nail off of FORE END, 2 x Type 1's OUTBOARD:- Duplex tree nails, Type 3 on crack in aft end (<).			
Wood Science: [rings, ARW, knots, sapwood, conversion] Radial at aft surf. c 55H ARW = 205/55. Pitt beyond lower edge?			
Recommended action: [samples, additional photos, moulding, queries and problems]			
Cleaned: OP/06/06	3J KMN VT	Recorded: TNJ 09.06.06	Photos:
Checked: [corrections needed]		Initials & Date: NN 14/6/6	
Corrections Done [desktop, Faro Arm?]:		Initials & Date:	