



DB 19/2/8

Cow Tag 237		Function Code 54.1
Brief Description: [timber element, p/s, condition, fragments] WELL PRESERVED PLANK, DAMAGED ON FORW. END		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos		
<p>Type 2</p> <p>6 INSCRIBED LINES OUTBD. FACE, AFT OF FORW. END 3 ROVES ON LOWER EDGE OF OUTBD. FACE 1 WOODEN SPIKE, UPPER EDGE, OUTBD., FORW. OF AFTEND SEVERAL ADDITIONAL NAILS FORW. OF AFT END 3 PLUGGED HOLES, LOWER EDGE, AFT OF FORW. END 2 Nail heads on inboard face, upper edge, " " "</p> <p>Type 3 damaged</p>		
Wood Science: [rings, ARW, knots, sapwood, conversion]		
<p>c85H. Tangential at aft scarf. → near radial at damaged forward end. ARW = 190/85</p>		
Recommended action: [samples, additional photos, moulding, queries and problems]		
<p>PHOTOS of outboard as indicated on plot</p>		
Cleaned:	Recorded:	Photos:
15.03.06 MHR, AK	15/5/06 VT	
Checked: [corrections needed]		Initials & Date:
NN. ✓		NN 16/5/6
Corrections Done [desktop, Faro Arm?]:		Initials & Date:

recorded by Vossels
 9/05/06



237 S4_1 Vassilis Tsakiris 15 May 2006

photos

photos

photos




photo of
clear enough!

substantial modern P&G.