

DB 19/2/8

Cow Tag

269

Function Code

517.4


Brief Description: [timber element, p/s, condition, fragments]

Long plank, bent in middle, forward scarf damaged

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

Offboard: Very interesting clamp marks on aft end. Additional nails on aft scarf
Several inscribed lines apart from t1/t3 also maybe t2
Inboard: clamp marks. t1, t5

At least 7




Sample # 2613

came off between cleaning + recording → location unknown
therefore it was not recorded.

| | | | | | | |
|-----|-----|-----|-----|-----|-----|-----|
| T.1 | T.2 | T.3 | T.4 | T.5 | T.6 | T.7 |
| ✓ | (?) | ✓ | | ✓ | | |

Wood Science: [rings, ARW, knots, sapwood, conversion]


c 110W Radial P. A. merlan
ARW = 230 / 110



Recommended action: [samples, additional photos, moulding, queries and problems]

| | | |
|--|------------------------------|--|
| Cleaned: VT/EV/MS/LB 11/09/06 | Recorded: TNS 12.09.06 | Photos: Clamp marks have been photo - 23/9/06 SE 1/5/08 |
| Checked: [corrections needed] | Initials & Date: NN 18/10/06 | |
| Corrections Done [desktop, Faro Arm?]: | Initials & Date: | |

simtols?



209 S17.4 Toby N. Jones 12 September 2006

