




DB 19/2/8

Cow Tag 271	Function Code S 23 4	
Brief Description: [timber element, p/s, condition, fragments] <p>THIS IS LOWER HALF</p> <p>edge of plank missing - covering in all of cracks, lots of wooden plugs</p>		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <p>INS. LINE 10cm off of cow tag</p> <p>" " 15cm for " "</p> <p>" " 70cm " "</p> <p>" " 1.5m off of for edge</p> <p>" " 5m off of and T.N from for edge</p> <p>Type ③ Line off of Forw. end</p> <p>Out. Att out - tool marks across whole s. de 3 additional nails approx 1m aft of forward edge cooking on fracture that runs whole length on upper edge - POSSIBLE "STAPLE-MARK" - ADD. NAIL-HOLES FILLED WITH CAULKING → NO CORROSION PRODUCTS</p> <p>ASSOCIATED TINGLE: 272</p>		
Wood Science: [rings, ARW, knots, sapwood, conversion] <p>NB. This ring cut etc applies to 271 + 1713 combined</p> <p>Radial. Pith uncertain as no clear growth trend. c75H</p> <p>ARW =</p> 		
Recommended action: [samples, additional photos, moulding, queries and problems] <p>- NICE NICE FACETTES + TOOL SIGNATURES OUTBD. → <u>MOULDING</u></p> <p>- TOOL SIGNATURES ARE VERY DIFFERENT TO THE ONES ON PLANKS ⇒ USE OF DIFF. TOOL (e.g.: AD2E)</p>		
Cleaned: ms/vi 3/10/6	Recorded: 04.08.06 AK	Photos:
Checked: [corrections needed] ✓		Initials & Date: NN 16/8/6
Corrections Done [desktop, Faro Arm?]:		Initials & Date:



271 823_4 Angeln Karsten 04 August 2006

Angeln 3

Angeln 1

Angeln 1

Angeln 1