


DB 11/3/8

Cow Tag 383 Function Code P79A

Brief Description: [timber element, p/s, condition, fragments]
section of Plank fairly good condition
Bow end of Plank - Forward scarf, damaged aft.

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos
Tool marks (possible) on out board side near on land edge and scarf - Diagonal
possible scribed line Aft of Forward edge on inboard running through treenail hole

Wood Science: [rings, ARW, knots, sapwood, conversion]
Radial. ~ 60H ARW = 205/60
Pith uncertain



Recommended action: [samples, additional photos, moulding, queries and problems]
Add additional nail inboard upper edge?

Cleaned: MS 27/4/6

Recorded: MS 6/4/5/6

Photos:

Checked: [corrections needed] ✓

Initials & Date: NN 23/8/6

Corrections Done [desktop, Faro Arm?]: ✓

Initials & Date: MN 23/8/6

RECORDING IN PROGRESS