




DB# 11/3/8

Cow Tag 398		Function Code P 3.9
Brief Description: [timber element, p/s, condition, fragments] FRAGMENT, NOT VERY WELL PRESERVED Forward scarf.		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos 2 PLUGGED HOLES ON EITHER SIDE OF TREENAIL TOWARDS UPPER + LOWER EDGE (MAYBE ONLY 1, CAUSE 1 IS DAMAGED BY A CRACK) - This is not a normal trail hole - diam of c36mm 1 ADDITIONAL NAIL AT # EDGE OF SCARF, INBD. NICE TOOL SIGNATURES ON INBD SCARF Outboard! also present on P 3.8 389 as m forward scarf		
Wood Science: [rings, ARW, knots, sapwood, conversion] Radial, c80H ARW= 210/80 Pith beyond upper edge?		
Recommended action: [samples, additional photos, moulding, queries and problems] POSSIBLE Moulding OF TOOL MARKS ON OUTBOARD AFT SCARF Photo of oversize hole and adjacent nails - see print out. NOT SUITABLE FOR DEND - too many cracks.		
Cleaned: 01.03.06 MMR, AK	Recorded: 28/04/06 SJ	Photos:
Checked: [corrections needed] /		Initials & Date: NN 23/8/6
Corrections Done [desktop, Faro Arm?]:		Initials & Date:

Records In Progress
BRJ



photos please



398

cofferdam