


DB 5/3/2008

Cow Tag	407	Function Code	S 15.6A
Brief Description: [timber element, p/s, condition, fragments]			
TRUNCATED PLANK - LOTS OF CRACKS Damaged forward part.			
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos			
INBOARD:- POSSIBLE TOOLMARKS ON CANO BELOW COMING			
OUTBOARD:- POSSIBLE TOOLMARKS 1 MET. AFT OF IN SITU TREEHALL			
Wood Science: [rings, ARW, knots, sapwood, conversion]			
Radial, Pith beyond lower edge SSH, ARW = 180/55.			
Recommended action: [samples, additional photos, moulding, queries and problems]			
Cleaned:	35	Recorded:	35
23/06/06		24/07/06	
Checked: [corrections needed]	Initials & Date:		
✓	NN 28/7/7		
Corrections Done [desktop, Faro Arm?]:	Initials & Date:		
	NN BS 28/7/7		