


DB 21/05/2010

Cow Tag <b>56</b> <del>Tangentially converted</del>		Type <b>Plank</b>
<p>Description <del>Radially split</del> plank - possibly a ship's timber, however no land or scarf. Measures 80cm in length, 22cm wide and 1.5cm thick. Two metal fasteners, nails no longer in situ. Holes measure 0.5cm x 0.5cm. Surfaces are in a dry, cracked state. Full length extent is unknown but width is original (ignoring shrinkage). Original number given is 223. Possible clench plate staining. However no impression. Lozenge shaped rusty staining measured 3cm x 4cm - *for recording purpose the surface with the possible clench plate staining has been called inboard, this orientation is not certain.</p>		
<p>Wood Science:</p> <p>Bark Yes <input type="radio"/> No <input checked="" type="radio"/> one knot</p> <p>Sapwood Yes <input type="radio"/> No <input checked="" type="radio"/> slow grown oak</p> <p>Knotty Yes <input type="radio"/> No <input checked="" type="radio"/> Approx 4 rings</p> <p>Straight grained <input checked="" type="radio"/> Yes <input type="radio"/> No <input checked="" type="radio"/> Tangentially converted, Distinct growth trend -</p>		
<p>Recommended action: [samples, additional photos, moulding, queries and problems]</p> <p><i>Discarded</i></p>		
<p>Checked: [corrections needed]</p> <p><i>NN 11/5/10</i></p>		
Cleaned:	Recorded: <i>EMC 15/4/10</i>	Photos: <input checked="" type="checkbox"/>


COW TAG SG OA SG EM 15/4/10




PROFILE



INBOARD



CROSS SECTION



SCALE 1:5