0B 13/3/8

Cow Tag 57	9	Function Code 53.P
Brief Description: [timber element, p/s, condition, fragments]		
QUITEWELL PRESERVED PLANK, ONLY SOME CRACKS		
AT AFT END, OUTBD		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK		
OUT FOR WHEN RECORDING ufos		
- 1 ADD. NAIL, LAND OUTB., TOWARDS AFT END + Inboard Fre		
- 2 ADD. NAIL AT AFT END OF PLANK - 2 WODEN PLUGS, LAND OUTB., TOWARDS BOW		
- 2 WODEN PLUGS, LAND OUTB., TOWARDS BOW		
-WIWOODEN PLUGA, LAND INBD., - AFT.		
Poly Coste 121 C		
Roughly finished inboard face		
3 Inscribed "diamonds" - outboard Face, Head of Aft cracks - Type 3.		
Wood Science: [rings, ARW, knots, sapwood, conversion]		
noticed Its for the leading		
Radial at aft scart. Pith bother mountain 60 H ARN= 198 60		
Pacammonded action: [samples additional photos moulding queries and		
problems]	iementoned)	C. t. t. see the a Mark
Recommended action: [samples, additional photos, moulding, queries and problems]  Photograph "diamonds" + faceto + signatures or although face		
I forest scort		
Cleaned:	Recorded:	Photos:
200		LB 03/08/2006
17.02.06. A K TNJ [7, March 2006] Checked: [corrections needed]		Initials & Date:
Onconed. [corrections needed]		NN 26/4/6
Operations Dans Idealton Fore April 1		
Corrections Done [desktop, Faro Arm?]:		Initials & Date:
		A CONTRACTOR OF THE CONTRACTOR

