

DB 21/2/18

Cow Tag

631

Function Code

F 62-0

Brief Description: [timber element, p/s, condition, fragments]

v. damaged floor element 'v' shaped, sliced in half by sheet piling

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

For - lots of see marks Pile damaged on port side  
I.B - see marks Hacked in antiquity on upper end of starboard arm.

~~Further core~~

Small round impression on 2nd Joggle outboard - starboard. - not sure what this is

T.1

T.2

T.3

T.4

T.5


T.6

T.7

T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]

>5, c70H + 10S + Be. on starboard side. Timber is from crown of tree



Recommended action: [samples, additional photos, moulding, queries and problems]

Photos: + 1B face

Core for deids after photos?

Cleaned:

14/12/06

Recorded:

25/11/07

Photos:

PM JV 18/1/08

Checked: [corrections needed]


/

Initials & Date:

NN 67/11/7.


Corrections Done [desktop, Faro Arm?]:

Initials & Date:



Forward


Scraper  
Case




Inboard

631 F62\_0 Matt Simmonds 25 January 2007

1m



Aft



Outboard