

DB 21/2/18



Cow Tag 032 Function Code F2-0

Brief Description: [timber element, p/s, condition, fragments]
floor timber, slight damage to extremities
very soft.

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING
Starboard side - Scarf joint on O.B. sole,
∴ F2-2 was put in place first,
groin V. Swirly - 1.3 - Saddle - back edge almost
groin quite difficult to see
low top on aft
sole) Scarfed over F2.1? ☺

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8
-----	-----	-----	-----	-----	-----	-----	-----

Wood Science: [rings, ARW, knots, sapwood, conversion]
External bark edge on wood face
Arises from two branches in crown.





Recommended action: [samples, additional photos, moulding, queries and problems]
Photos: angled 'feet' and timber hole showing from
floor is not coated. + Near horizontal Trunnel on aft
face


Cleaned: JS
19/01/07 Lewis
 Recorded: 08/02/07 JS
 Photos: 8/1/2008 SC, SU, PM

Checked: [corrections needed]
✓
 Initials & Date:
NN 22/10/7

Corrections Done [desktop, Faro Arm?]:
 Initials & Date:



632 F2_0 Ben R. Jennings 09 February 2007



Searched over F2.1

