

Cow Tag 637	Function Code FSI-0
-------------	---------------------

Brief Description: [timber element, p/s, condition, fragments]
 Intact, good condition

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

Sapwood on aft and forward faces 3 rebated TN's on port arm.

Axe marks on inboard.

Possible tie lines

No Bevel on forward face around the timber hole.

Some nail angles + depths are suspect on outboard face.

3cm pin for nail angle scarf small add nail

Rebated Fe nails on forward edge 18 faced each scarf.


" timber hole on aft face.

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8
			⚡				

Wood Science: [rings, ARW, knots, sapwood, conversion]

Be on aft port arm + forward starboard arm. Starboard

$C + 3.5H + 10S + Be = 130 / 45$



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: EW EWC 1/3/07	Recorded: 06/03/2007 TNJ	Photos:
--------------------------------------	-----------------------------	---------

Checked: [corrections needed] ✓	Initials & Date: MN 5/2/8.
------------------------------------	-------------------------------

Corrections Done [desktop, Faro Arm?]:	Initials & Date:
----------------------------------------	------------------