

JB 21/05/2010

Cow Tag 63 Type function- unknown

Description 20cm x 20cm x 3cm. One treenail - 2.7cm in diameter, still in situ. Second treenail hole (partial) appears to have diameter of 2.7cm also but is damaged. Some metal staining on outboard surface. However no metal fasteners. Inboard surface is in poor condition. No landmarks remain. original wood number 230.

Wood Science:


Bark Yes  No

Sapwood Yes  No

Knotty Yes  No

Straight grained Yes  No

Possibly elm ✓<sup>10/19</sup>  
Tangentially faced ✓✓




Recommended action: [samples, additional photos, moulding, queries and problems]  
Discarded ✓


Checked: [corrections needed]  
NN 11/10

Cleaned: Recorded: EMC 27/4/10 Photos: ✓


OUTBOARD



PROFILE



INBOARD



CROSS SECTION

