

DB 19/11/09

T11

T119.

Cow Tag 658 658	Function Code F 17-2
----------------------------	----------------------


Brief Description: [timber element, p/s, condition, fragments]
 fragments of frame

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

unable to orientate. from an area of a pile ~~significant~~ link to F17.2. Looks to be planking

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 07/12/09 38	Recorded:	Photos:
-------------------------	-----------	---------

Checked: [corrections needed]	Initials & Date:
-------------------------------	------------------

Corrections Done [desktop, Faro Arm?]:	Initials & Date:
--	------------------

DB 19/11/09


Cow Tag 658 Function Code P&S Plank Misc limb

Brief Description: [timber element, p/s, condition, fragments]
Associated with Frames 17-2
Damaged at one end

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned:	Recorded: <u>11/12/07 DV</u>	Photos:
----------	---------------------------------	---------

Checked: [corrections needed]	Initials & Date:
-------------------------------	------------------

Corrections Done [desktop, Faro Arm?]:	Initials & Date:
--	------------------