




Cow Tag 098	Function Code 59.2	
Brief Description: [timber element, p/s, condition, fragments] COMPLETE PLANK		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <p>MANY AX MARKS VISIBLE ON ^{FACE OF FORWARD} OUTBOARD SCARF, AND OUTBOARD LAND.</p> <p>5 GROUPS OF INTENTIONAL MARKS ALONG INBOARD FACE OF PLANK. (1 modern?)</p> <p>1 EXTRA NAIL AT STERN END OF PLANK.</p> <p>1 EXTRA NAIL AT CENTRE, LOWER EDGE.</p> <p>Small wooden plugs at aft scarf.</p>		
Wood Science: [rings, ARW, knots, sapwood, conversion] <p>No ^{end} grain visible on forward edge. rays far from straight!</p> <p>c70 H + S</p> <p>ARW = 197 / 90</p> <p>NOT good for dendro with spiral grain?</p> 		
Recommended action: [samples, additional photos, moulding, queries and problems] <p>Photograph nails adjacent to trenails (x2).</p> <p>Note no additional nails at aft scarf not visible (but must be present!).</p>		
Cleaned: ✓	Recorded: ✓ TNS 11/4/15 TNS 13/1/17.	Photos:
Checked: [corrections needed]		Initials & Date: NN 17/5/15
Corrections Done [desktop, Faro Arm?]:		Initials & Date:



wedges

the trained
the wedges
the rings



missed
nail (wooden)

needs close examination
- relationship

COWTAG
098