



Figs 37 & 38 (below). Brackenridge OF. The collapsed first floor in the north-east corner of the main house (above) and along the north wall, showing original timbers.





Figs 39 & 40 (below). Original timbers, still in place (right) or re-used (left) supported on the replacement partition wall. The re-used beam below has been turned so the chamfer is on the top left instead of the bottom.







Figs 41 & 42; details of carpentry.



Fig 43 The recently sawn-off end of the original east-west beam supporting the first floor in the main house.



Fig 44 An exterior door, found in the main house, with horizontal planking. This may be the original front door.





Fig 45. Brackenridge Field Barn. South elevation.



Fig 46. Brackenridge Field Barn. Detail of entrance with date.






Fig 47 Brackenridge Field Barn, east elevation.




Fig 48 Brackenridge Field Barn, west elevation.



Fig 49. Brackenridge Field Barn. North elevation.