



PLATE 1 WELL HALL FROM THE WEST



PLATE 2 WELL HALL UNDERCROFT WING FROM THE EAST



PLATE 3 WELL HALL SOUTH WING FROM THE EAST



PLATE 4 UNDERCROFT FLOOR AT COMMENCEMENT OF WORK



PLATE 5
TEST HOLE AT BASE
OF WESTERN PILLAR,
UNDERCROFT



PLATE 6 BRICK PATH, UNDERCROFT




PLATE 7 SLATE FEATURE AND RISE IN GROUND, UNDERCROFT



PLATE 8
SLATE FEATURE
EXCAVATED,
UNDERCROFT



PLATE 9 WEST WINDOW BAY, UNDERCROFT



PLATE 10 ASHPIT FEATURE, UNDERCROFT



PLATE 11 LIME FLOOR, UNDERCROFT




PLATE 12 LIME FLOORS AND ASHPIT, UNDERCROFT



PLATE 13 BRICK AND DECAYED WOOD NEAR CENTRAL PILLAR



PLATE 14 LIME FLOOR NEAR SOUTH DOOR



PLATE 15
ALTERED AND
BLOCKED
SOUTH DOORWAY




PLATE 16 UNDERCROFT FLOOR BENEATH RUBBLE FILL



PLATE 17
BASE OF EASTERN
COLUMN

PLATE 18
EASTERN ALCOVE
LOOKING NORTH



PLATE 19
EASTERN ALCOVE
LOOKING SOUTH



PLATE 20 DRESSED STONES AT NORTH END OF EASTERN ALCOVE - ?START OF
STAIR