

---

## 10.0 Appendix 3 ~ The Plates.

---



*Plate 1. General view of bridge and support structure from the south.*



*Plate 2. Bridge viewed from the north, showing the failure of the arch and damage to the abutment.*





Plate 3. The east abutment viewed from the south, showing the failure of the lower portion.




Plate 4. The 'date stone' recovered from Kex Beck.





*Plate 5. Contexts (1000) (1001) (1002) (1003) and (1006) viewed from the south.*



*Plate 6. The exposed vault of the arch (1006) viewed from the east.*





*Plate 7. One of the reused copings viewed from the south.*



*Plate 8. Possible cruck timber in Kex Beck, viewed from the north.*