



HISTORIC BUILDING SURVEY

PHOTO ARCHIVE

Northern Archaeological Associates Ltd

Registered Office:

Marwood House
Harmire Enterprise Park
Barnard Castle
Co. Durham
DL12 8BN

t: 01833 690800

w: www.naaheritage.com

STABLE AND CART SHED
ASSOCIATED WITH FORMER
PROVINCIAL LAUNDRIES
COMPLEX, PROVIDENCE ROW,

prepared for

Kier Construction

on behalf of

Durham County Council

Project No.: 1436

Text: Lydia Loopesko

Illustrations: Damien Ronan

NAA 19-02
January 2019

ID no.	context number	photograph	name	initial	date
1	1100	1100-3100_total_view.JPG	stable exterior	II	01/08/2018
2		1100-3100_total_view-2.JPG	stable exterior	II	01/08/2018
3	1110	1110_lk_e.JPG	north elevation	II	01/08/2018
4	1111	1110-2110_lk_e.JPG	stable door	II	01/08/2018
5	1112	1112_side-door_lk_se.JPG	side door	II	01/08/2018
6		1112_stable_door_lk_se.JPG	side door	II	01/08/2018
7	1113	1113_east_window_lk_se.JPG	windows	II	01/08/2018
8	1114	1114_vents_lk_s.JPG	vents	II	01/08/2018
9	1130	1130_lk_nw.JPG	east elevation	II	01/08/2018
10		1130_lk_w.JPG	east elevation	II	01/08/2018
11	1210	1210_stable_lk_e.JPG	stable interior	II	01/08/2018
12		1210_stable_lk_n.JPG	stable interior	II	01/08/2018
13		1210_stable_lk_n1.JPG	stable interior	II	01/08/2018
14		1210_stable_lk_ne.JPG	stable interior	II	01/08/2018
15		1210_stable_lk_ne1.JPG	stable interior	II	01/08/2018
16		1210_stable_lk_nw.JPG	stable interior	II	01/08/2018
17		1210_stable_lk_s.JPG	stable interior	II	01/08/2018
18		1210_stable_lk_s1.JPG	stable interior	II	01/08/2018
19		1210_stable_lk_se.JPG	stable interior	II	01/08/2018
20		1210_stable_lk_se-1.JPG	stable interior	II	01/08/2018
21		1210_stable_lk_sw.JPG	stable interior	II	01/08/2018
22		1210_stable_lk_w.JPG	stable interior	II	01/08/2018
23	1211	1211_stall-grooves_lk_s.JPG	stall grooves	II	01/08/2018
24		1211_stall-grooves_lk_w.JPG	stall grooves	II	01/08/2018
25	1213	1213_side-drain_lk_se.JPG	side drain	II	01/08/2018
26	1218	1218_stairs_lk_se.JPG	stairs	II	01/08/2018
27	1220	1220_attic_lk_e.JPG	attic	II	01/08/2018
28		1220_attic_lk_n.JPG	attic	II	01/08/2018
29		1220_attic_lk_n1.JPG	attic	II	01/08/2018
30		1220_attic_lk_ne.JPG	attic	II	01/08/2018
31		1220_attic_lk_ne1.JPG	attic	II	01/08/2018
32		1220_attic_lk_nw.JPG	attic	II	01/08/2018
33		1220_attic_lk_nw1.JPG	attic	II	01/08/2018
34		1220_attic_lk_s.JPG	attic	II	01/08/2018
35		1220_attic_lk_se.JPG	attic	II	01/08/2018
36		1220_attic_lk_sw.JPG	attic	II	01/08/2018
37		1220_attic_lk_sw2.JPG	attic	II	01/08/2018
38		1220_attic_lk_w.JPG	attic	II	01/08/2018
39	1224	1224_trusses_lk_sw1.JPG	trusses	II	01/08/2018
40		1224_trusses_lk_w.JPG	trusses	II	01/08/2018
41		1224_trusses_lk_w1.JPG	trusses	II	01/08/2018
42		1224_trusses_lk_w2.JPG	trusses	II	01/08/2018
43	1230	1230_side-room_lk_n.JPG	side room	II	01/08/2018
44		1230_side-room_lk_ne.JPG	side room	II	01/08/2018
45		1230_side-room_lk_ne1.JPG	side room	II	01/08/2018
46		1230_side-room_lk_s.JPG	side room	II	01/08/2018
47		1230_side-room_lk_s1.JPG	side room	II	01/08/2018
48		1230_side-room_lk_sw.JPG	side room	II	01/08/2018
49	1231	1231_chimney_lk_se.JPG	fireplace	II	01/08/2018
50	2100	2100-3100_lk_s.JPG	exterior	II	01/08/2018
51	2110	2110_lk_se.JPG	cart shed north elevation	II	01/08/2018
52		2110_lk_sw.JPG	cart shed north elevation	II	01/08/2018
53	2111	2111_lk_sw.JPG	doors	II	01/08/2018
54	2120	2120-3130_lk_e.JPG	south elevation	II	01/08/2018

55	2121	2121_pipe_lk_nw.JPG	pipe	II	01/08/2018
56	2130	2130_lk_e.JPG	east elevation	II	01/08/2018
57	2200	2200_cart-shed_lk_w.JPG	interior	II	01/08/2018
58	2201	2201_roof-trusses_lk_nw.JPG	roof trusses	II	01/08/2018
59	2202	2202_roof-lights_lk_s.JPG	roof lights	II	01/08/2018
60		2202_roof-lights_lk_w.JPG	roof lights	II	01/08/2018
61	2203	2203_east-door_lk_ne.JPG	doors	II	01/08/2018
62		2203_west-door_lk_nw.JPG	doors	II	01/08/2018
63	3110	3100_lk_sw.JPG	outbuilding north elevation	II	01/08/2018
64	3111	3111_door_lk_sw.JPG	east door	II	01/08/2018
65	3112	3112_door_lk_sw.JPG	west door	II	01/08/2018
66	3113	3113_window.JPG	window	II	01/08/2018
67	3114	3114_vent_lk_sw.JPG	vent	II	01/08/2018
68	3120	3120_lk_s.JPG	outbuilding west elevation	II	01/08/2018
69	3130	3130_lk_ne.JPG	outbuilding south elevation	II	01/08/2018



1_1000-3000_total_view



2_1000-3000_total_view-2



3_1110_lk_e



4_1110-2110_lk_e



5_1112_side-door_lk_se



6_1112_stable_door_lk_se



7_1113_east_window_lk_se



8_1114_vents_lk_s



9_1130_lk_nw



10_1130_lk_w



11_1210_stable_lk_e



12_1210_stable_lk_n



13_1210_stable_lk_n1



14_1210_stable_lk_ne



15_1210_stable_lk_ne1



16_1210_stable_lk_nw



17_1210_stable_lk_s



18_1210_stable_lk_s1



19_1210_stable_lk_se



20_1210_stable_lk_se-1



21_1210_stable_lk_sw



22_1210_stable_lk_w



23_1211_stall-grooves_lk_s



24_1211_stall-grooves_lk_w



25_1213_side-drain_lk_se



26_1218_stairs_lk_se



27_1220_attic_lk_e



28_1220_attic_lk_n



29_1220_attic_lk_n1



30_1220_attic_lk_ne



31_1220_attic_lk_ne1



32_1220_attic_lk_nw



33_1220_attic_lk_nw1



34_1220_attic_lk_s



35_1220_attic_lk_se



36_1220_attic_lk_sw



37_1220_attic_lk_sw2



38_1220_attic_lk_w



39_1224_trusses_lk_sw1



40_1224_trusses_lk_w



41_1224_trusses_lk_w1



42_1224_trusses_lk_w2



43_1230_side-room_lk_n



44_1230_side-room_lk_ne



45_1230_side-room_lk_ne1



46_1230_side-room_lk_s



47_1230_side-room_lk_s1



48_1230_side-room_lk_sw



49_1231_chimney_lk_se



50_2100-3100_lk_s



51_2110_lk_se



52_2110_lk_sw



53_2111_lk_sw



54_2120-3130_lk_e



55_2121_pipe_lk_nw



56_2130_lk_e



57_2200_cart-shed_lk_w



58_2201_roof-trusses_lk_nw



59_2202_roof-lights_lk_s



60_2202_roof-lights_lk_w



61_2203_east-door_lk_ne



62_2203_west-door_lk_nw



63_3100_lk_sw



64_3111_door_lk_sw



65_3112_door_lk_sw



66_3113_window



67_3114_vent_lk_sw



68_3120_lk_s



69_3130_lk_ne