20th Century Naval Dockyards Devonport and Portsmouth 6265 Record Form Figure nos relate to the published Report		Portsmouth Dockyard Archive: HE Building Ref: 1/66 Building Name: St Ann's Church Grid Reference: SU 63171 00567		
Archive name and address	HE Archive, The Engine House, Fire Fly Aver	ue, Swindon S	SN2 2EH	
Visit date	27 November 2012			
Document	Red Box 1738 Hampshire: Portsmouth Churches A-St B			
reference	Ned Box 1730 Hampshire. Fortsmodeli endi	ches // St B		
Subject	St Ann's Church Portsmouth Dockyard			
Summarise the	Relevant b/w photos			
salient points of the	, ,			
document				
Identify whether it sh	nould be copied for data: Yes/No		Yes	
Identify whether an i			Yes	
If Yes explain why, as	succinctly as possible (its relevance to technology	ology/		
	d development/other/where it fits into the la	rger picture)		
Give indication of imp	portance: Core/Secondary/Nil 1738/33 good picture of St Ann's bomb dan		Core Evidence of Second World War bombing and subsequent repair and redesign.	
clearly as possible, transcribed extracts or folio/page references/images (acquired electronically or by photocopy) which you consider should feature in the Report text, explaining why	volume 1, p. 63, which is not a very clear reproduction) Date 1942 Photographer per Rev C H R Cocup Rec. 20.4.48 Brief History 1738/41 (2pp) St Ann's Church E 48/39 Reconstruction Drawing 1939, signed Diana V. Cundall 1948: West, East elevations; detail of Cupola; Cross sectional A-A looking west; Longitudinal section B-B, Cross sectional A-A looking east.			
	St Ann's Church E 48/40 Reconstruction Drawing 1939, signed Diana V. Cundall 1948: North Elevation, 1785/1939 Plan 1785/1939			
	Showing an extension at the west end			
Researcher initials	AVC Updates/initials AVC	7.3.16		
Relationship to which building/ structure, if known	See Coats <i>et al.</i> (2015), p. 132:			
	East of Storehouse No. 17 is St Ann's Church (1785, 1/66, Grade II, 1386817, CA 22, MoD, SU 63171 00567). Air raids on 17–18 April and 3 May 1941 badly damaged the west end, roof beams and east window:			
	The first, in April 1941, demolished the north-west corner of the church. A fortnight later, blast from a second bomb entered the open space at the west end and caused further damage inside the church. Two days later small pieces of brick and other materials began to fall from the west wall, and later another part tumbled to the ground, taking with it main roof beams and the belfry. (HE NMR, 1738/41)			

	vest end was clad in corrugated iron until 1955, repaired by A. E. Cogswell Son, supervised by M. J. Dew and Mr Hodgeman, using the original ngs, with new drawings by Diana V. Cundall but sixteen feet shorter. The grose survived the bombing. Fragments of the east window were reused in morial fanlight shield by Hugh Easton over the north door. A new east ow was designed by Easton showing a bird's eye view of the dockyard in funded by an appeal through the <i>News</i> and an Admiralty grant, dedicated 47. The Chaplain's offices were built in 1961. (Lambert, 1993; Smith, 2001, 2-14, 16-18) Together with Devonport Naval Barracks HMS <i>Drake</i> Chapel of holas (1905–7, Grade II, 1386364), it still holds services.	
	Fig. 323. E 48/39. Detail of the west elevation of St Ann's Church, Portsmouth. Reconstruction Drawing 1939, signed Diana V. Cundall. Reproduced by permission of Historic England.	
	Fig. 324. E 48/39. Detail of Cupola, St Ann's Church, Portsmouth. Reconstruction Drawing 1939, signed Diana V. Cundall. Reproduced by permission of Historic England.	
References	Coats, A., Davies, J. D., Evans, D., and Riley, R. (2015). 20th Century Naval Dockyards: Devonport and Portsmouth Characterisation Report. Portsmouth: Naval Dockyards Society. ISBN 978-0-9929292-0-6; ebook ISBN 978-0-9929292-2-0.	
	The Report is free to download on the Naval Dockyards Society website: http://navaldockyards.org/c20-naval-dockyards/	
	Wessex Archaeology (2004). Historic Dockyard, Portsmouth, Hampshire. Conservation Statement (2 volumes). Salisbury: Wessex Archaeology.	