| 20th Century Naval Dockyards Devonport and Portsmouth 6265 Record Form | | Portsmouth Dockyard Archive: PCC HER Building Ref: 1/23 Building Name: Boathouse No. 6 Grid Reference SU 630466 004237 Building Ref: 1/6 Building Name: Boathouse No. 4 Grid Reference SU 629213 003577 | |
|--|---|---|--|
| Archive name and address | Historic Environment Record, Muse | ums, Archives | & Visitor Services |
| | City Development and Cultural Services, City Museum | | |
| Visit data | Museum Road Portsmouth PO1 2LJ 9 January 2013 | | |
| Visit date Document reference | Site Activity PM 40; Source PM 38, SAS 168. | | |
| Subject | Southern Archaeological Services (1999). Summary Report on an Archaeological Watching Brief at Boathouse No. 6 and the Recording of Boathouse No. 4 Locks, Portsmouth Dockyard Hampshire. Southampton | | |
| Summarise the salient points of the document | Southern Archaeological Services Ltd. An archaeological watching brief was completed and reported by Southern Archaeological Services Ltd during refurbishment in 1999. Two trenches were dug (Fig. 2): Trench 1 inside at the eastern end where piles were excavated for the new cinema; Trench 2 outside, on the southern approach, where the new staircase was installed. | | |
| | Finds from Trench 2: 3 fragments of post-medieval earthenware pottery, fragments of post-medieval and Modern pantiles, early Modern and Modern peg-tiles and roof tiles; 59 fragments of clay tobacco pipes early C18 and mid-C19; 2 fragments of onion bottle bases; 20 fragments of iron nails and bolts; 24 shavings of <i>Pinus</i> sp., <i>Quercus</i> sp.; a stake of possibly <i>Castanea</i> cf. <i>sativa</i> , 1 fragment of charcoal and 2 oyster shell valves. A cobbled surface was found at the northern section of Trench 2, part of a road, path or hardway post-dating the boathouse. A line of north-south stakes cutting part of Trench 2, associated with a decayed wooden spread, indicates control of water flow. (pp. 2, 7-11) | | |
| Identify whether it should be | copied for data: Yes/No | | Yes |
| Identify whether an image should be included in the Report: Yes/I If Yes explain why, as succinctly as possible (its relevance to technology/ dockyard development/other/where it fits into the la | | ology/ | Yes |
| Give indication of importance | | | Core. Confirms that the area presently occupied by Boathouse No. 6 has been used for boatbuilding for a considerable period. (Southern Archaeological Services, 1999, pp. 2, 7-11) |
| Abstracted or transcribed extracts; folio/page references/listed images (acquired electronically or by photocopy) which should feature in the Report text. Researcher initials | pp. 1-18 Maps/Figures 2-11 Figure 2. Plan of Boathouse No. 6, s archaeological features. See Coats <i>et al.</i> (2015), p. 122. AVC Updates/initial | | observed and |
| Relationship to other | Boathouse No. 4 Locks | | |

| building/structure | |
|--------------------|---|
| References | Coats, A., Davies, J. D., Evans, D., and Riley, R. (2015). 20th Century Naval Dockyards: Devonport and Portsmouth Characterisation Report. Portsmouth: Naval Dockyards Society. ISBN 978-0-9929292-0-6; ebook ISBN 978-0-9929292-2-0. |
| | The Report is free to download on the Naval Dockyards Society website: http://navaldockyards.org/c20-naval-dockyards/ |
| | Southern Archaeological Services (1999). Summary Report on an Archaeological Watching Brief at Boathouse No. 6 and the Recording of Boathouse No. 4 Locks, Portsmouth Dockyard Hampshire. Southampton Southern Archaeological Services Ltd. |