## PHOTOGRAPHIC SURVEY OF BARNS AT HIGHCLIFFE FARM, SOUTH CLIFF ROAD, KIRTON IN LINDSEY, NORTH LINCOLNSHIRE

NGR: SK 9414 9716 North Lincolnshire Site Code: KLAV Planning ref: 2006/0068



Report prepared for Mr. Garry Cooper

by Chris Clay April 2007

Allen Archaeological Associates
Unit 1c, Branston Business Park
Lincoln Road
Branston
LN4 1NT
Tel.: 01522 794400

Tel.: 01522 794400 E-mail: allenarchaeology@btconnect.com www.allenarchaeology.co.uk



## Contents

1.0	Introduction	2
2.0	Site location and description	2
3.0	Planning background	2
4.0	Methodology	2
5.0	Results 5.1 Barn 1 5.2 Barn 2	3 3 4
6.0	Acknowledgements	6
7.0	References	6
8.0	The Plates 8.1 Barn 1 8.2 Barn 2	7 7 13
Appe	endix 1: Photographic archive list	15

## **List of Figures**

- Figure 1: Site location at scale 1:25,000
- **Figure 2:** Plan of the barns at scale 1:150, showing the position of all photographs taken with film number and frame number (black arrows indicate black and white shots, red arrows indicate colour slides). Black and white shots F.1 pl. 27, 28 and colour slides F.2 pl.9 12 are not shown as they were taken from beyond the edge of the plan to the south and south-south-west. Photographs taken on the first floor of Barn 2 are shown on Figure 3.
- **Figure 3:** Plan of the first floor of Barn 2 at scale 1:150, showing the position of all photographs taken with film number and frame number (black arrows indicate black and white shots, red arrows indicate colour slides).

## **List of Plates**

- **Plate 1:** Northern elevation, looking south, showing the area of collapse around the central door of Barn 1, and the northern gable end of Barn 2.
- **Plate 2:** Detail of the north elevation of Barn 1, showing a blocked window and a scar indicating a former X shaped tie (scale 1m).
- Plate 3: Eastern elevation of Barn 2, looking west.
- **Plate 4:** Detail showing the three bay opening (possible former cartshed) at the north end of Barn 2. Looking north-east.
- Plate 5: Detail showing blocked doorway in the east elevation of Barn 2. Looking west (scale 0.5m)
- **Plate 6:** Western gable end of Barn 1 fronting South Cliff Road. Note the brick sawtooth quoins and tumbling. Looking east.
- Plate 7: South elevation of Barn 1, looking east-north-east from the west end of the building.
- Plate 8: Detail of door and blocked windows in south elevation of Barn 1, looking north (scale 1m).
- **Plate 9:** Detail showing door and window at the east end of the south elevation of Barn 1, looking north (scale 1m).
- Plate 10: South elevation of Barn 2, looking north-east.
- **Plate 11:** General view of large room at the west end of Barn 1. Looking east-south-east from the north-west corner. The brick foundations of the pig sties are clearly visible as are the wooden and steel tie beams in the roof.
- **Plate 12:** General view of large room at the west end of Barn 1. Looking west-south-west from the north east corner. Again, the former pig sties and the roof supports are visible.
- **Plate 13:** Detail showing the brickwork of the dividing wall between the two rooms at the east end of Barn 1, looking east. A number of 'airholes' are also visible.
- Plate 14: General view of room at the east end of Barn 1, looking north-north-west from the south-east corner.
- **Plate 15:** View of the doorway in the west wall of the room at the east end of the barn. The modern concrete around the door frame suggests that it is a recent addition or alteration. Looking west (scale 1m).
- **Plate 16:** Interior of Barn 2, looking north. The workshop area is visible in the background, with the former hayloft above.
- **Plate 17:** First storey room at the north end of Barn 2, looking south-south-east towards the doorway and a blocked window.
- Plate 18: Interior east elevation of Barn 2, showing blocked ventilation holes. Looking south-west.
- Plate 19: Roof structure of Barn 2, looking south from the hayloft/ mezzanine.
- **Plate 20:** General view of the site, looking north-north-east. The west end of Barn 1 fronts onto the road. Barn 2 is in the background. The building in the foreground is a modern breeze block pig shed, due for demolition.
- Plate 21: North elevation of the barns, looking south.
- Plate 22: Barn 2, looking south-west. Part of Barn 1 is also visible extending to the west.
- Plate 23: West gable end of Barn 1, looking east from South Cliff Road.
- Plate 24: South elevation of Barn 1. Looking north-west, showing the two doors and the blocked windows.