

**PHOTOGRAPHIC SURVEY AND WATCHING BRIEF REPORT:
HOMEFIELD FARM, ASHBY CUM FENBY,
NORTH-EAST LINCOLNSHIRE**

NGR: TA 2532 0031
Planning ref: DC/922/06/WAB
Site Code: ACF07



Report prepared for
Mr J. Coupland

by Chris Clay
June 2007

Allen Archaeological Associates
Unit 1c, Branston Business Park
Lincoln Road
Branston
LN4 1NT
Tel.: 01522 794400
E-mail: allenarchaeology@btconnect.com
www.allenarchaeology.co.uk



Contents

1.0	Introduction	2
2.0	Site location and description	2
3.0	Planning background	2
4.0	Archaeological and historical background	2
5.0	Methodology	3
6.0	Photographic survey results	3
7.0	Watching brief results	5
8.0	Acknowledgements	6
9.0	References	6
10.0	The Plates	7
	Appendix 1: Photographic archive list	12
	Appendix 2: List of archaeological contexts	13

List of Figures

Figure 1: Site location at scale 1:25,000

Figure 2: Site location plan, with the barns outlined in red (scale 1:2500)

Figure 3: Plan of the barns, showing the location of all photographs (black arrows), and the extent of the groundworks (outlined in red) (scale 1:200)

List of Plates

Plate 1: The barn complex, looking south-south-west

Plate 2: North elevations of Buildings 1 and 2, looking south

Plate 3: East elevation of Building 1, looking west-south-west

Plate 4: South elevation of Building 1, looking north-north-west. This elevation has been repointed and has a breeze block supporting wall to its rear. The restored roof is also visible.

Plate 5: East elevation of Buildings 2 and 3, looking west across the crew yard. Note the roof scar denoting a former outbuilding over the large door of Building 3, and the blocked doorway in Building 2. This shot also clearly shows the different brickwork used in the lower part of Building 2.

Plate 6: West elevation of Buildings 2 and 3, looking east-north-east. Again, the roof scar of a former outbuilding is visible, and the red bricks forming the earliest part of Building 2.

Plate 7: Interior of northernmost room in Building 2, looking north

Plate 8: Interior of central room in Building 2, looking south-east

Plate 9: Detail of west elevation of Building 3, looking east-north-east and showing the ventilation holes, the roof scar of the former outbuilding and the blocked pitching hole.

Plate 10: Interior shot of Building 3 and the southern room of Building 2, looking south-south-east. The new wall is visible in the foreground.

Plate 11: East elevation of Building 4, looking west-south-west.

Plate 12: North elevation of Building 4, looking south-south-east. Note the blocked windows towards the west end of the elevation.

Plate 13: South elevation of Buildings 3 and 4, looking north-north-west.

Plate 14: Interior of easternmost room in Building 4, looking north. Note the buttressing of the north wall.

Plate 15: Soakaway on the west side of Building 2, showing the drain or culvert running below the building. Looking east-north-east.