

Appendix 1: Colour plates (Archive shot numbers are in brackets, see Figures 4, 5, and 6 for shot location and direction)



Plate 1: (001) Southern façade of the Greyhound Inn demonstrating the limitations upon photographic recording. Looking north.



Plate 2: (009) The Western Elevation showing the ashlar cladding. Note the location of the Western Range stack behind the gable coping. The tarpaulin covers fire damage to the second floor. Looking south-east.



Plate 3: (178) Northern elevations showing the false garret bullseye window in the Eastern Range and the visually intrusive lean to abutting the atrium frame. Looking south-east.



Plate 4: (013) The eastern elevations of the Eastern Range, detailing remodelling at the eaves and the insertion of dormers into the roof. Looking south-west.



Plate 5: (014) North elevation of the courtroom showing the high level moulded stone window and rear access steps with steps down to the cellar doorway. Looking south



Plate 6: (026) Eastern elevation of the Western Range (South Block) illustrating the changes in wall fabric associated with phases of development. Looking north-west



Plate 7: (021) Western (internal) elevation of the East Range (South Block). Looking east.



Plate 8: (027) Northern elevation of the carriageway arch with 19th century infilling on the ground floor. Note the offset of the ashlar blockwork facia, in the right hand corner, necessary to correct the alignment between the Southern and Western Ranges. Looking south.