

## Stone Hall Barn, Matching, Essex.



Owners digital 66 - to E showing the entry into the midstrey with storey posts and the slightly cranked arch braces to the tiebeams. note the scarf in the wallplate is a face halved and bladed as appears in the aisle wallplate.



Owners digital 48 - to E showing storey post to midstrey with added iron tie to midstrey wallplate.



Owners digital 25 - to N showing third arcade post to aisle side and edge halved and bridled scarfs to the arcade plate.



Owners digital 27 - to NE showing the lower part of third arcade post with sill return to aisle.



Owners digital 17 - to W showing top of arcade post, cranked arch braces and the edge halved and bridled scarfs to the plate. Note the reuse of crown post roof rafters in the construction that have most likely come from an earlier domestic building as they show signs of sooting from an open fire.



Owners digital 76 - to NE showing the roof end construction with half hip. The hip rafters rise to a very high set saddle not leaving space for gablet ventilation.