



Main details added to outline shape from customer drawings. No detail frame survey available. All timber positions sketched in.

R =Repair timber

West side visible frame of barn