

View into midstrey roof, built a single bay unit with purlins framed front and rear and birds mouth collar between. Purlins converted from one tree sawn through the centre. These again suggest possible coppice growth pattern.



Possible original elm weatherboarding trapped by the lean-to roof. Still in good condition.