



Photo 172. Inside view looking to the north west with concrete grain silos & associated operating gear and walkways. Original aisle tie to left replacement to right. Brace problems to right arcade plate.



Photo 208. Inside view above aisle level looking to the south east with heavy duty trunking on arch braces, crown strut from tiebeam to collar with extra part truss with serpentine bracing at mid bay.