



Photo 76. One of two bays with original walling. Wall D, Bay 1 - 3. Good relatively large section timber typical of middle sixteenth century. Later door inserted in nineteenth century. Aisle roof rebuilt as is end wall.



Photo 78. View in direction of arrow above showing aisle tie and shore with extra shore but brace to return sill missing.



Photo 191. View from midstrey looking north with 2 silos removed. Aisles rebuilt nineteenth century.



Photo 48. Typical ridge joint to main trusses showing swelled end of reduced principal rafters.