



Photo 187. Samples of bricks with small scratched out frogs suggesting a manufacture about the turn of the nineteenth century. Plenty of inclusions and left brick over fired but right brick about correct and size is 9" x 4.375" x 2.75" with horizontal pressure marks again suggesting very early nineteenth century. All laid in lime mortar.



Photos.

185

183

181.

VIEW TO AISLE WALL INSIDE BAYS 3 - 5 ON WALL D. THE AREA IS ENCLOSED AND ROOFED TO THE HEIGHT AND WIDTH OF THE AISLE.

The wall is original to the barn, has been infilled with brick on edge in the early nineteenth century and the lower part lined with sawn elm boarding. (Appears to be a reciprocating saw for the original and circular sawn for replacements) This boarding extends around all sides but the lower area has been covered with corrugated sheets at a later date sometime in the twentieth century. A clamp has been attached to the aisle plate to support the roof joists for a board cover. A door has been cut in from the midstre and the building with its careful sealing appears to have been an internal granary.

Feeringbury barn, Feeringbury, Essex.